



report date: 2024-03-29

General information

Make	SUZUKI
Model	JIMNY SZ3
Colour	White
Year of manufacture	2015
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-22
Pictures	40
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-20
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	8
Total items failed	7

MOT #13	2024-04-27 09:02
MOT test number	486904075872
Result	✓ Passed
Next expiry date	2025-05-20
Advice	All metal brake pipes and some fuel pipes are badly rusted very strongly advise to attend to them

MOT #12	2024-04-27 09:02
MOT test number	888178565462
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))
Advice	All metal brake pipes and some fuel pipes are badly rusted very strongly advise to attend to them

MOT #11	2023-05-09 11:58
MOT test number	798914599245
Result	✓ Passed

**MOT #10** 2023-05-05 11:23**MOT test number** 959860270385**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2022-05-10 13:35**MOT test number** 867414780346**Result** ✓ Passed**MOT #8** 2022-05-10 11:28**MOT test number** 249194818185**Result** ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MOT #7** 2021-05-21 08:43**MOT test number** 693572071491**Result** ✓ Passed**MOT #6** 2021-01-21 14:50**MOT test number** 559443486871**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2021-01-20 13:14**MOT test number** 697941376622**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Axle king pin is loose in the axle beam (5.1.2 (d) (i))**MOT #4** 2020-01-15 13:00**MOT test number** 391192075380**Result** ✓ Passed**MOT #3** 2019-02-08 12:49**MOT test number** 174568599985**Result** ✓ Passed**MOT #2** 2018-02-05 12:09**MOT test number** 111416006354**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2018-02-05 10:30**MOT test number** 227513318910**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
20 May 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	20 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-02-14
Last registration	2024-04-27
Complete history	See info



Registration #1	2015-02-14	10 mi
Registration #2	2018-02-05	63.507 mi
Registration #3	2018-02-05	63.507 mi
Registration #4	2019-02-08	85.361 mi
Registration #5	2020-01-15	105.250 mi
Registration #6	2021-01-20	120.443 mi
Registration #7	2021-01-21	120.444 mi
Registration #8	2021-05-21	126.236 mi
Registration #9	2022-05-22	151.277 mi
Registration #10	2022-05-22	151.277 mi
Registration #11	2022-05-22	151.277 mi
Registration #12	2022-05-22	151.277 mi
Registration #13	2022-05-22	151.277 mi
Registration #14	2022-05-22	151.277 mi
Registration #15	2022-05-22	151.277 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3665 mm
Wheel base	2250 mm
Kerb weight	1135 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2357242