



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN

**MOT history**

MOT #18	2022-10-20 11:37
MOT test number	646079645728
Result	✓ Passed
Next expiry date	2023-10-22
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #17	2021-10-08 07:07
MOT test number	423469447809
Result	✓ Passed

MOT #16	2020-10-09 12:59
MOT test number	698490347284
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2020-10-09 12:59
MOT test number	946030319159
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2019-04-18 13:39**MOT test number** 975452127215**Result** ✓ Passed**MOT #13** 2019-04-18 09:35**MOT test number** 581622903796**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed 225-50/17 (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge worn and tyre perished (5.2.3 (e))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #12** 2018-04-23 11:10**MOT test number** 146959635277**Result** ✓ Passed**MOT #11** 2018-02-26 10:09**MOT test number** 904227819187**Result** ✓ Passed**MOT #10** 2017-03-14 11:08**MOT test number** 625703887352**Result** ✓ Passed**Advice** Engine covers fitted and under trays fitted

**MOT #9**

2017-03-13 12:57

MOT test number

882372837853

Result**✗ Failed****Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Engine covers fitted and under trays fitted**Fail** Nearside Headlamp aim too low (1.8)**MOT #8**

2016-02-05 12:00

MOT test number

758980234482

Result**✓ Passed****Advice** Engine covers fitted not allowing inspection of some components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Undertrays fitted not allowing inspection of some components**Advice** Brake disc worn, pitted or scored, but not seriously weakened All (3.5.1i)**MOT #7**

2016-02-05 09:21

MOT test number

379681371445

Result**✗ Failed****Advice** Engine covers fitted not allowing inspection of some components**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Undertrays fitted not allowing inspection of some components**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Brake disc worn, pitted or scored, but not seriously weakened All (3.5.1i)

**MOT #6** 2015-01-17 09:36**MOT test number** 426127015082**Result** ✓ Passed**Notice** (2) Both rear tyres deteriorated close to limit on outer sidewalls.**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** (1) Front number plate damage close to limit.**Notice** (3) Front brake pads worn close to limit.**Notice** (1) Windsrceen damaged close to limit.**MOT #5** 2015-01-17 09:36**MOT test number** 358467115060**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** (1) Windsrceen damaged close to limit.**Notice** (2) Both rear tyres deteriorated close to limit on outer sidewalls.**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** (1) Front number plate damage close to limit.**Notice** (3) Front brake pads worn close to limit.**MOT #4** 2014-02-12 09:50**MOT test number** 269623944085**Result** ✓ Passed**Notice** Front registration plate damaged close to limit.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Both rear tyre outer side walls perished close to legal limits.

**MOT #3**

2014-02-10 16:32

MOT test number

769711844043

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Front registration plate damaged close to limit.**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Both rear tyre outer side walls perished close to legal limits.**Notice** Front bumper slightly damaged.**MOT #2**

2013-01-28 12:45

MOT test number

499698923058

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1**

2013-01-28 12:45

MOT test number

325768323036

Result**✗ Failed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-15
Last registration	2022-10-20
Complete history	See info



Registration #1	2009-12-15	11 mi
Registration #2	2013-01-28	34.811 mi
Registration #3	2014-02-10	45.290 mi
Registration #4	2014-02-12	45.290 mi
Registration #5	2015-01-17	49.126 mi
Registration #6	2016-02-05	69.087 mi
Registration #7	2016-02-05	69.087 mi
Registration #8	2017-03-13	80.772 mi
Registration #9	2017-03-14	80.772 mi
Registration #10	2018-03-20	80.772 mi
Registration #11	2018-03-20	80.772 mi
Registration #12	2018-03-20	80.772 mi
Registration #13	2018-03-20	80.772 mi
Registration #14	2018-03-20	80.772 mi
Registration #15	2018-03-20	80.772 mi
Registration #16	2018-03-20	80.772 mi
Registration #17	2022-10-20	11 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	613349
---------------	--------