




report date: 2024-03-28

General information

Make	AUDI
Model	A5 TDI DPF S LINE
Colour	Silver
Year of manufacture	2009
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





## Internet history

### Entry 1

Date	2021-06-05
Pictures	17
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	14

MOT #16	2023-05-10 12:33
MOT test number	970375300349
Result	✓ Passed
Next expiry date	2024-05-31

MOT #15	2022-05-17 17:00
MOT test number	276299909780
Result	✓ Passed
<b>Advice</b>	Steering column universal joint has slight wear or play (2.2.2 (c))
<b>Advice</b>	Rear Shock absorbers has light misting of oil both (5.3.2 (b))

MOT #14	2022-05-09 13:16
MOT test number	105720851197
Result	✗ Failed
<b>Advice</b>	Steering column universal joint has slight wear or play (2.2.2 (c))
<b>Fail</b>	Nearside Front Lower Suspension arm insecurely attached rear / ball joint loose (5.3.3 (a) (i))
<b>Advice</b>	Rear Shock absorbers has light misting of oil both (5.3.2 (b))

MOT #13	2021-05-10 15:39
MOT test number	714918083292
Result	✓ Passed



**MOT #12** 2021-05-06 08:54

**MOT test number** 469285353218

**Result** ✗ Failed

- Fail** Undertray likely to become detached (6.2.1 (a) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Front Windscreen washer not working (3.5 (a))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #11** 2020-06-01 12:02

**MOT test number** 810409055783

**Result** ✓ Passed



<b>MOT #10</b>	2020-03-02 14:34
<b>MOT test number</b>	191733474294
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))
<b>Fail</b>	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Advice</b>	Steering column universal joint has slight wear or play (2.2.2 (c))
<b>Minor</b>	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
<b>Advice</b>	Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #9</b>	2019-01-16 14:51
<b>MOT test number</b>	101966557815
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2019-01-09 13:37
<b>MOT test number</b>	373047533762
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



**MOT #7** 2018-01-18 09:35

**MOT test number** 678910488234

**Result** ✓ Passed

**MOT #6** 2017-03-20 10:06

**MOT test number** 541235268327

**Result** ✓ Passed

**MOT #5** 2016-03-17 14:21

**MOT test number** 298320291484

**Result** ✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-04-22 09:37

**MOT test number** 996432215120

**Result** ✓ Passed

**MOT #3** 2014-04-11 11:35

**MOT test number** 798471904182

**Result** ✓ Passed

**Advice** Nearside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #2** 2013-04-16 14:48

**MOT test number** 948836303134

**Result** ✓ Passed

**MOT #1** 2012-04-04 11:20

**MOT test number** 446415692090

**Result** ✓ Passed




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	<b>SH09KXT</b>
Plate since	2024-03-28
Current registration	<b>SH09KXT</b>
Plate since	2024-03-28

More info >



**Finance check**

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	18
<b>First mileage registration</b>	2009-04-21
<b>Last registration</b>	2023-05-10
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2009-04-21	15 mi
<b>Registration #2</b>	2012-04-04	57.205 mi
<b>Registration #3</b>	2013-04-16	75.806 mi
<b>Registration #4</b>	2014-04-11	94.489 mi
<b>Registration #5</b>	2015-04-22	99.694 mi
<b>Registration #6</b>	2016-03-17	102.995 mi
<b>Registration #7</b>	2017-03-20	107.035 mi
<b>Registration #8</b>	2018-01-18	110.972 mi
<b>Registration #9</b>	2019-01-09	118.853 mi
<b>Registration #10</b>	2019-05-20	121.277 mi
<b>Registration #11</b>	2019-09-20	123.701 mi
<b>Registration #12</b>	2020-03-20	126.125 mi
<b>Registration #13</b>	2020-07-20	128.549 mi
<b>Registration #14</b>	2021-01-20	130.973 mi
<b>Registration #15</b>	2021-05-20	133.397 mi
<b>Registration #16</b>	2021-09-20	135.821 mi
<b>Registration #17</b>	2022-03-20	138.245 mi
<b>Registration #18</b>	2023-05-10	140.669 mi

[More info >](#)



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1854 mm
Height	1372 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1470 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	CAH 025597