





General information

Make	CITROEN
Model	DS3 PURETECH DSTYLE PLUS S/S
Colour	White
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	В







Internet history

Entry	1
Date	

Pictures

2022-03-11

3

Listing price

View report







source: cargurus.co.uk



WN15EAA report date: 2024-03-29

MOT history

MOT expiry date	2024-04-22
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	23
Total items failed	1

MOT #9	2023-03-28 13:34
MOT test number	665909020272
Result	✓ Passed
Next expiry date 20	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

МОТ #8	2022-04-04 15:08
MOT test number	126216331515
Result	✓ Passed

MOT #7	2022-04-01 07:07
MOT test numbe	er 404437061517
Result	× Failed
DANGEROUS (a) (ii))	Front Brake disc in such a condition that it is seriously weakened worn and pitted (1.1.14
DANGEROUS	Nearside Rear Tyre has ply or cords exposed cracked (5.2.3 (d) (ii))
MAJOR Offsic	de Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR Offsic	de Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
DANGEROUS (ii))	Rear Brake disc in such a condition that it is seriously weakened worn and pitted (1.1.14 (a)
DANGEROUS	Offside Rear Tyre has ply or cords exposed cracked (5.2.3 (d) (ii))
MAJOR Nears	side Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))





2020-04-23 10:50

MOT #6		2021-04-14 14:43
MOT test	number	777970888883
Result		✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessi	ve movement (5.3.4
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Windscreen wiper blade defective (3.4 (b) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive	e movement (5.3.4 (a)
Advice	Engine oil leak	

MOT #5

MOT test number	520419165526
Result	✓ Passed
Advice Both rear tyres side wall badly perishing	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #4	2020-04-20 08:28	
MOT test number	130352804451	
Result	× Failed	
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Both rear tyres side wall badly perishing		
Pass with rectification Offside Headlamp aim too low (4.1.2 (a))		





MOT #3		2019-03-19 10:12
MOT test	number	975083558804
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MOT #2		2019-03-19 09:09
MOT test	number	881189743944
Result		🗙 Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	

MOT #1	2018-03-12 15:58
MOT test number	690996586363
Result	✓ Passed



wn15EAA report date: 2024-03-29

Tax & MOT check

	✓ Taxed		Х МОТ
Tax due: 1 June 2024		Expired: 22 April 2024	
Tax status			Valid until 1 June
Days left			33
MOT expiry date			22 April 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

venicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMPL
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-17
Last registration	2023-03-28
Complete history	<u>See info</u>



Registration #1	2015-04-17	24 mi
Registration #2	2018-03-12	15.173 mi
Registration #3	2019-03-19	21.261 mi
Registration #4	2019-03-19	21.261 mi
Registration #5	2020-04-20	27.303 mi
Registration #6	2020-04-23	27.313 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 est
Registration #11		





Safety ratings

NCAP rating	****
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight	
Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1070 kg
Max. allowed weight	1578 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3