





General information

Make	CITROEN
Model	DS3 BLUEHDI DSIRE
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A







Internet history


Entry 1

Date Pictures 2021-08-02

37

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	16
Total items failed	1

MOT #11	2023-08-31 13:45
MOT test number	251345799450
Result	Passed
Next expiry date	2024-08-30
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #10	2023-08-31 13:45
MOT test number	554066097475
Result	× Failed
Pass with rectification(4.7.1 (b) (ii))AdviceFront Exhaust hat	Registration plate lamp inoperative in the case of a single lamp or all lamps as a minor leak of exhaust gases (6.1.2 (a))
MOT #9	2022-08-26 11:37

MO1 #9	2022-00-20 11.37
MOT test number	663495699607
Result	✓ Passed

MOT #8	2021-08-25 15:53
MOT test number	877697363048
Result	✓ Passed



NK64U	FV
report date: 202	24-03-28

MOT #7		2021-08-03 08:06
MOT test	number	823906307598
Result		🗙 Failed
MAJOR the ingress	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no lo s of dirt (6.1.7 (g) (ii))	onger prevents
MAJOR the ingress	MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
MAJOR	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
MOT #6		2021-04-21 15:14
MOT test	number	297295534488
Result		🗸 Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))

MOT #5	2020-03-31 10:31
MOT test number	948175250931
Result	✓ Passed

MOT #4		2019-04-09 13:44
MOT test	number	387970529343
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



NK64UFV report date: 2024-03-28

MOT #3	2019-04-09 11:08
MOT test number	389502588484
Result	🗙 Failed
MAJOR Exhaust system insecure (6.1.2 (a))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3	(e))
MAJOR Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.	.3 (e))
MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
DANGEROUS Rear Brake disc in such a condition that it is seriously weakened (1.3)	1.14 (a) (ii))
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2018-04-11 11:59
MOT test number	991075735321
Result	✓ Passed
MOT #1	2017-08-14 15:25

MOT test number	199548243483
Result	✓ Passed



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 30 August 2024	✓ MOT
Tax status			Valid until 1 August
Days left			95
MOT expiry date			30 August 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	
Band		٨	

Band	А
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	 · · ·
Category	 AMPL
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates	5.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-01
Last registration	2023-08-31
Complete history	See info



Registration #1	2014-09-01	25 mi
Registration #2	2017-08-14	30.306 mi
Registration #3	2018-04-11	33.405 mi
Registration #4	2019-04-09	42.493 mi
Registration #5	2019-04-09	42.493 mi
Registration #6	2020-03-31	46.143 mi
Registration #7	2021-04-21	47.334 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		
		11.777 est
Registration #12		11.227 es





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1598 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 3