



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-10-29
Pictures	8
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #19	2022-10-19 12:07
MOT test number	205695473876
Result	✓ Passed
Next expiry date	2023-11-17
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases center section (6.1.2 (a))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #18	2022-10-19 12:07
MOT test number	183579143241
Result	✗ Failed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases center section (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2021-10-25 13:45

MOT test number

450348003823

Result

✓ Passed

- Advice** Parking brake lever defective but can be satisfactorily operated high advise adjustment (1.1.6 (d))
- Advice** Rear sub frame and forward mounting plates have surface corrosion advise coating to prevent further corrosion
- Advice** Offside Front head light faded slight light reduction
- Advice** Rear Coil spring corroded n/s and o/s slight (5.3.1 (b) (i))
- Advice** Nearside Front some fixing clips on front bumper not located still secure
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing has some perishing on tread (5.2.3 (d) (ii))

MOT #16

2020-10-28 13:06

MOT test number

165880405434

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Nearside front bumper slightly damaged
- Advice** Rear Coil spring corroded BOTH (5.3.1 (b) (i))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Over sills fitted
- Advice** Exhaust corroded
- Minor** Headlamp lens slightly defective BOTH (4.1.1 (b) (i))



MOT #15

2020-10-27 12:19

MOT test number

487109498882

Result

✗ Failed

DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Exhaust corroded**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside front bumper slightly damaged**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))**Minor** Headlamp lens slightly defective BOTH (4.1.1 (b) (i))**Advice** Rear Coil spring corroded BOTH (5.3.1 (b) (i))**Advice** Over sills fitted

MOT #14

2019-10-30 13:53

MOT test number

235025668836

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2019-10-30 08:16

MOT test number

586962584021

Result

✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12

2018-10-24 06:25

MOT test number

838393053679

Result

✓ Passed

**MOT #11** 2018-10-24 06:25**MOT test number** 607357387079**Result** ✗ Failed**Pass with rectification** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #10** 2017-10-26 06:27**MOT test number** 115672061249**Result** ✓ Passed**MOT #9** 2017-10-26 06:27**MOT test number** 728952731789**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Pass with rectification** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #8** 2016-11-03 08:53**MOT test number** 310438923717**Result** ✓ Passed**MOT #7** 2015-11-18 08:21**MOT test number** 449717971337**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-11-16 14:52**MOT test number** 229997719807**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-10-24 15:55**MOT test number** 907627594263**Result** ✓ Passed**MOT #4** 2013-10-23 14:14**MOT test number** 938636393231**Result** ✓ Passed**MOT #3** 2013-10-22 10:29**MOT test number** 538345593241**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover missing (2.4.G.2)

**MOT #2** 2012-10-20 11:30**MOT test number** 648184992232**Result** Passed**Advice** Offside Anti-roll bar has slight play in a ball joint (2.4.G.2)**Notice** Slight blow on front pipe**Advice** Nearside Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** N/s/r tyre punctured and run flat**MOT #1** 2011-10-25 14:37**MOT test number** 368578391220**Result** Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted to n/s/r seat unable to check seat belt



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DV58URU
Plate since	2019-03-29
Current registration	DV58URU
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-11-05
Last registration	2022-10-19
Complete history	See info



Registration #1	2008-11-05	28 mi
Registration #2	2011-10-25	28.570 mi
Registration #3	2012-10-20	34.336 mi
Registration #4	2013-10-22	40.281 mi
Registration #5	2013-10-23	40.281 mi
Registration #6	2014-10-24	47.163 mi
Registration #7	2015-11-16	53.062 mi
Registration #8	2015-11-18	53.068 mi
Registration #9	2016-11-03	69.249 mi
Registration #10	2017-10-26	85.650 mi
Registration #11	2017-10-26	85.650 mi
Registration #12	2018-10-26	85.650 mi
Registration #13	2018-10-26	85.650 mi
Registration #14	2018-10-26	85.650 mi
Registration #15	2018-10-26	85.650 mi
Registration #16	2018-10-26	85.650 mi
Registration #17	2018-10-26	85.650 mi
Registration #18	2018-10-26	85.650 mi
Registration #19	2018-10-26	85.650 mi
Registration #20	2018-10-26	85.650 mi
Registration #21	2018-10-26	85.650 mi
Registration #22	2018-10-26	85.650 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564