



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 S
Colour	Grey
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-30
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	82
Total items failed	16

MOT #172023-11-29 17:24

MOT test number181239682239

Result✓ Passed

Next expiry date2024-11-30

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases silencer splitting (6.1.2 (a))

**MOT #16**

2023-11-29 14:14

MOT test number

346993977641

Result**✗ Failed**

Advice Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases silencer splitting (6.1.2 (a))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #15**

2022-11-23 16:51

MOT test number

956639428783

Result

✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Brake hose has slight corrosion to ferrule All (1.1.12 (f) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14

2022-11-23 15:42

MOT test number

854142208701

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Brake hose has slight corrosion to ferrule All (1.1.12 (f) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #13**

2021-11-30 11:26

MOT test number

216552039230

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on edges 185-65-15 (5.2.3 (e))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear axle and all suspension components rusted
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

2021-11-30 11:26

MOT test number

705287751778

Result

✗ Failed

- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Rear axle and all suspension components rusted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on edges 185-65-15 (5.2.3 (e))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2020-12-01 12:37**MOT test number** 780173182386**Result** ✓ Passed**MOT #10** 2019-10-31 14:55**MOT test number** 610687577982**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-10-25 15:34**MOT test number** 329341554095**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust mounting defective (6.1.2 (a))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2018-10-25 13:10**MOT test number** 978436053832**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Central Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #7** 2017-10-18 14:49**MOT test number** 254715672834**Result** ✓ Passed

- Advice** Offside Front tyre side wall cracked
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front number plate cracked

MOT #6 2017-10-18 13:44**MOT test number** 382223982731**Result** ✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Front number plate cracked
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front tyre side wall cracked



MOT #5	2016-10-29 10:25
MOT test number	216651927865
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front tyre cracked

MOT #4	2016-10-29 08:53
MOT test number	407383407581
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Offside Front tyre cracked
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2015-10-26 14:11**MOT test number** 923031916134**Result** ✓ Passed

- Advice** All tyres cracking badly on outer sidewalls no cords visible
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Slight oil leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2014-10-31 14:04**MOT test number** 545544304396**Result** ✓ Passed

- Notice** Both rear tyres cracking badly on sidewall and in tread no cords visible
- Notice** O/s/r tyre slightly cracking on sidewall

MOT #1 2013-10-12 11:09**MOT test number** 949595983276**Result** ✓ Passed

- Notice** Front Brake discs slightly corroded
- Notice** Rear Exhaust mount snapped, still adequately supported



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	NA60HYX
Plate since	2024-03-28
Current registration	NA60HYX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-10-16
Last registration	2023-11-29
Complete history	See info



Registration #1	2010-10-16	18 mi
Registration #2	2013-10-12	13.254 mi
Registration #3	2014-10-31	16.222 mi
Registration #4	2015-10-26	19.258 mi
Registration #5	2016-10-29	23.080 mi
Registration #6	2016-10-29	23.030 mi
Registration #7	2017-10-18	27.375 mi
Registration #8	2017-10-18	27.375 mi
Registration #9	2018-10-25	33.021 mi
Registration #10	2018-10-25	33.021 mi
Registration #11	2019-10-25	33.021 mi
Registration #12	2019-10-25	33.021 mi
Registration #13	2019-10-25	33.021 mi
Registration #14	2019-10-25	33.021 mi
Registration #15	2019-10-25	33.021 mi
Registration #16	2019-10-25	33.021 mi
Registration #17	2019-10-25	33.021 mi
Registration #18	2019-10-25	33.021 mi
Registration #19	2019-10-25	33.021 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1215 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FSW86309213