





report date: 2024-03-29

General information

Make	AUDI
Model	A5 TDI QUATTRO SPORT
Colour	Silver
Year of manufacture	2010
Top speed	138 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 258 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-27

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

MOT expiry date	2024-02-07
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	48
Total items failed	3

MOT #15		2023-02-08 11:51
MOT test	number	334035179436
Result		✓ Passed
Next expi	ry date	2024-02-07
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Fuel filler flap door not secure	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps (i))	s or light sources

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #14		2022-01-31 17:10
MOT test	number	398357771130
Result		✓ Passed
Advice	Rear Exhaust heat shield insecure	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Fuel filler flap door not secure	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #13 2022-01-29 11:58

MOT test number 537985695975

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Fuel filler flap door not secure

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Headlamp aim not tested (4.1.2 (b))

Advice Rear Exhaust heat shield insecure

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #12 2021-01-19 14:11

MOT test number 247697692978

MOT #11 2021-01-19 11:09

MOT test number 956672044423

Result X Failed

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #10 2019-07-11 11:24

MOT test number 404227418730

MOT #9 2019-07-11 08:37

MOT test number 795488504460

Result X Failed

MAJOR Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #8 2018-09-07 14:01

MOT test number 730542257285

Result Passed

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Service due

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement

rear (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2017-09-07 13:14

MOT test number 796901089210

Result Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2016-09-07 11:50

MOT test number 476196754887

Result

Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #5 2016-09-07 08:25

MOT test number 608965969563

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice N/s front tyre close to limit

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #4 2015-06-20 09:57

MOT test number 289101475177

Result ✓ Passed

Notice Advise o/s front tyre close to limit (2mm)

Notice No dipstick fitted

Notice Advise front brake pads close to limit

Notice Advise n/s and o/s rear tyre wearing on inner edges

MOT #3 2014-06-24 17:15

MOT test number 125355674145

Result \(\sqrt{Passed} \)

Notice Both rear tyres tread slightly distorted at inner shoulders.

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Front registration plate deteriorating.

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #2 2014-06-24 14:57

MOT test number 155065574110

Result ★ Failed

Notice Engine management light on.

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Front registration plate deteriorating.

Notice Both rear tyres tread slightly distorted at inner shoulders.

Fail Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1 2013-02-18 10:48

MOT test number 159409043045

Result ✓ Passed

Notice Rear registration plate deteriorating.

CarCheck.co.uk page 8/15



AG59NUK
report date: 2024-03-29

Tax & MOT check



Tax expired: 3 February 2024

X MOT

Expired: 7 February 2024

Tax status	Expired at 3 February 2024
Days left	85 days too late
MOT expiry date	7 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 9/15




report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report		re?
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Format matchesting		
Cornent registration	UK C	
Plate since		
Current registration	NE UK	
Rindo clara	UK C	
	More info	>

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-02-23
Last registration	2023-02-08
Complete history	See info



Registration #1	2010-02-23	15 mi
Registration #2	2013-02-18	51.401 mi
Registration #3	2014-06-24	77.557 mi
Registration #4	2014-06-24	77.557 mi
Registration #5	2015-06-20	93.674 mi
Registration #6	2016-09-07	101.402 mi
Registration #7	2016-09-07	101.402 mi
Registration #8	2017-09-07	108.015 mi
Registration #9	2018-09-07	111.735 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 ms

More info >

CarCheck.co.uk page 14/15



AG59NUK
report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1465 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number CBB 158548