



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Black
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





## Internet history

### Entry 3


Date	2022-03-12
Pictures	4
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date	2021-11-03
Pictures	4
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2022-05-04
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	10

MOT #10 2022-05-03 11:17

MOT test number 866378971672

Result ✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9 2021-05-05 16:17

MOT test number 798216776418

Result ✓ Passed

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

**Advice** Parking brake lever worn, but not excessively (1.1.6 (b) (i))

**MOT #8**

2021-05-04 14:33

**MOT test number**

863246673818

**Result**

✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Front Registration plate inscription missing broken (0.1 (b))
- Fail** Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

**MOT #7**

2020-03-16 11:36

**MOT test number**

683897321470

**Result**

✓ Passed

- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Advice** Plastic cover fitted top of the engine and under the floor
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

**MOT #6**

2019-03-21 12:22

**MOT test number**

299397115143

**Result**

✓ Passed

**MOT #5** 2018-03-20 11:36**MOT test number** 412080915594**Result** ✓ Passed**Advice** Nearside Rear lens slightly damaged**Advice** Tyre worn close to the legal limit both front and both rear (4.1.E.1)**MOT #4** 2017-03-22 12:03**MOT test number** 432564547596**Result** ✓ Passed**MOT #3** 2016-03-14 09:12**MOT test number** 661483343284**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Engine cover and under shield fitted.**MOT #2** 2015-03-18 08:58**MOT test number** 317537075066**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Notice** Headlamp masks/converters fitted**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-03-18 12:16**MOT test number** 119477574474**Result** ✓ Passed



## Tax &amp; MOT check

×

**Untaxed**

**Tax expired:**  
19 December 2022

×

**MOT**

**Expired:**  
4 May 2022

## Tax status

Expired at 19 December 2022

## Days left

498 days too late

## MOT expiry date

4 May 2022

## Full MOT history

[See MOT history](#)

## Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-24
Last registration	2022-05-03
Complete history	<a href="#">See info</a>



Registration #1	2011-03-24	26 mi
Registration #2	2014-03-18	55.993 mi
Registration #3	2015-03-18	76.142 mi
Registration #4	2016-03-14	91.538 mi
Registration #5	2017-03-22	106.643 mi
Registration #6	2018-03-20	125.091 mi
Registration #7	2019-03-21	137.620 mi
Registration #8	2020-05-03	150.149 mi
Registration #9	2021-05-03	162.678 mi
Registration #10	2022-05-03	175.207 mi
Registration #11	2023-05-03	187.736 mi
Registration #12	2024-05-03	200.265 mi
Registration #13	2025-05-03	212.794 mi
Registration #14	2026-05-03	225.323 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1044305