





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT EXECUTIVE TDI BLUEMOTION TECHN
Colour	Red
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	10.0 seconds
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-29
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8		2023-11-14 11:44
MOT test	number	457786733800
Result		✓ Passed
Next expi	ry date	2024-11-29
Advice Rear end k	Offside Front Lower Suspension arm pin or bush worn but not resulting in bush $(5.3.4 (a) (i))$	excessive movement
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weake	ned (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))

MOT #7	2022-11-22 10:38
MOT test	number 393262842517
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6		2021-11-25 14:12
MOT test	number	823408272442
Result		✓ Passed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #5 2021-11-25 10:54

MOT test number 811660214856

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #4 2020-11-30 12:49

MOT test number 124610938048

Result ✓ Passed

MOT #3 2019-08-20 07:48

MOT test number 878994805554

Result \(\sqrt{Passed} \)

MOT #2 2018-08-13 09:39

MOT test number 971107465376

Result ✓ Passed

MOT #1 2017-08-17 08:15

MOT test number 303441983203

Advice Emissions to clean to detect

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Damage 2

Category

Type

Date

Туре



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.	· · · · · · · · · · · · · · · · · · ·	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	***************************************	
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
See in this check if this VOLKSWAGEN had different number plates.		More info >
	Plate changes	
Plate since	See in this check if this VOLKSWAGEN had different number plates.	
Plate since	Number of plates	
UK UK	Current registration	UK UK
	Plate since	
Plate since	Current registration	UK UK
	Plate since	

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-01
Last registration	2023-11-14
Complete history	See info



Registration #1	2014-09-01	17 mi
Registration #2	2017-08-17	42.439 mi
Registration #3	2018-08-13	53.352 mi
Registration #4	2019-08-20	61.668 mi
Registration #5	2020-11-30	68.788 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		10.777 46
•		

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1471 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CFFBK74752