



report date: 2024-03-29

General information

Make	VOLVO
Model	V50
Colour	Green
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-25
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-15
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	14
Total items failed	9

MOT #20	2023-10-21 06:59
MOT test number	855662879370
Result	✓ Passed
Next expiry date	2024-10-26

MOT #19	2023-10-21 06:59
MOT test number	245348942993
Result	✗ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Offside Side repeater not working (4.4.1 (a) (ii))
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #18	2022-10-15 08:20
MOT test number	739969973192
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2022-10-15 08:20**MOT test number** 162314485006**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #16** 2021-10-27 16:31**MOT test number** 456302502427**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2021-08-26 10:12**MOT test number** 668334288727**Result** ✓ Passed**MOT #14** 2020-09-03 13:08**MOT test number** 540453822250**Result** ✓ Passed**MOT #13** 2020-09-03 08:40**MOT test number** 582345633094**Result** ✗ Failed**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #12** 2019-08-28 13:07**MOT test number** 485777235718**Result** ✓ Passed

**MOT #11** 2019-08-28 08:07**MOT test number** 414461761790**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Upper Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Play in steering rack inner joint(s)**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-08-28 08:42**MOT test number** 310784043521**Result** ✓ Passed**MOT #9** 2017-08-30 07:49**MOT test number** 527359669705**Result** ✓ Passed**MOT #8** 2016-08-23 15:24**MOT test number** 502706279699**Result** ✓ Passed

**MOT #7** 2016-08-23 08:48**MOT test number** 301969535746**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Upper Rear position lamp(s) not working (1.1.A.3b)**MOT #6** 2015-08-25 12:02**MOT test number** 785027335242**Result** ✓ Passed**Notice** Hand brake travel close to limit??**Notice** Front inner brake pads wearing low??**Notice** O/s front door damaged?**MOT #5** 2014-08-25 09:43**MOT test number** 506727134265**Result** ✓ Passed**MOT #4** 2013-09-06 08:41**MOT test number** 377279043493**Result** ✓ Passed**Notice** Front tyres low**MOT #3** 2012-09-04 11:11**MOT test number** 848948642283**Result** ✓ Passed



MOT #2	2012-01-30 09:15
MOT test number	255080432065
Result	✓ Passed

MOT #1	2011-08-11 14:13
MOT test number	158013921255
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LR58KJU
Plate since	2024-03-29
Current registration	LR58KJU
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-09-05
Last registration	2023-10-21
Complete history	See info



Registration #1	2008-09-05	12 mi
Registration #2	2011-08-11	6.226 mi
Registration #3	2012-01-30	7.423 mi
Registration #4	2012-09-04	12.192 mi
Registration #5	2013-09-06	18.627 mi
Registration #6	2014-08-25	24.574 mi
Registration #7	2015-08-25	30.989 mi
Registration #8	2016-08-23	36.871 mi
Registration #9	2016-08-23	36.871 mi
Registration #10	2017-08-30	42.775 mi
Registration #11	2018-08-28	46.615 mi
Registration #12	2019-08-28	50.651 mi
Registration #13	2020-08-28	55.000 mi
Registration #14	2021-08-28	59.000 mi
Registration #15	2022-08-28	63.000 mi
Registration #16	2023-08-28	67.000 mi
Registration #17	2024-08-28	71.000 mi
Registration #18	2025-08-28	75.000 mi
Registration #19	2026-08-28	79.000 mi
Registration #20	2027-08-28	83.000 mi
Registration #21	2028-08-28	87.000 mi
Registration #22	2029-08-28	91.000 mi
Registration #23	2030-08-28	95.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Number of seats

4

Engine number

143891