



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Grey
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-08-01
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-10
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	27
Total items failed	27

MOT #23	2024-01-12 11:26
MOT test number	353278845193
Result	✓ Passed
Next expiry date	2025-02-10
Advice	Rear Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))

MOT #22	2024-01-11 15:14
MOT test number	229303569342
Result	✗ Failed
Advice	Rear Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))
Fail	Front Direction indicator incorrect colour bothsides (4.4.3 (a))
Fail	Parking brake inoperative on one side (1.4.1 (a))
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Emissions unable to be completed exhaust leaking (8.2.1.2 (d))

**MOT #21** 2023-01-13 12:19**MOT test number** 644585522931**Result** ✓ Passed**Advice** Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**Minor** Front Headlamp lens slightly defective Both (4.1.1 (b) (i))**MOT #20** 2023-01-13 12:19**MOT test number** 181741205188**Result** ✗ Failed**Minor** Front Headlamp lens slightly defective Both (4.1.1 (b) (i))**Pass with rectification** Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))**MOT #19** 2022-02-03 12:53**MOT test number** 822494613296**Result** ✓ Passed**Advice** Front Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2022-01-27 15:26

MOT test number

674045382966

Result

✗ Failed

Fail Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt bothsides (5.3.4 (b) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Front Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))**MOT #17**

2021-02-11 12:52

MOT test number

285568099457

Result

✓ Passed

MOT #16

2020-01-18 13:17

MOT test number

888004899736

Result

✓ Passed

MOT #15

2020-01-16 13:24

MOT test number

727949811123

Result

✗ Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Headlamp not working on dipped beam and offside front (4.1.1 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases silencer (6.1.2 (a))**Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Nearside Front Headlamp not working on main beam and offside front (4.1.1 (a) (ii))

**MOT #14**

2019-01-19 09:40

MOT test number

781598566638

Result

✓ Passed

Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13

2019-01-18 11:43

MOT test number

927156027069

Result

✗ Failed

Fail

Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Nearside Rear Inner Tyre worn close to legal limit/worn on edge ADVISE TO CHANGE (5.2.3 (e))

Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2018-02-21 10:46

MOT test number

454605708034

Result

✓ Passed

MOT #11

2017-04-18 10:14

MOT test number

737926734585

Result

✓ Passed

Advice

Nearside Front Play in steering rack inner joint(s)

Advice

Exhaust has a minor leak of exhaust gases front flexi (7.1.2)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #10**

2017-04-12 09:43

MOT test number

603804168060

Result**✗ Failed****Fail**

Nearside Front front brake excessively fluctuating (3.7.B.3)

Advice

Nearside Front Play in steering rack inner joint(s)

Advice

Exhaust has a minor leak of exhaust gases front flexi (7.1.2)

Fail

Parking brake lever has no reserve travel (3.1.6b)

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #9

2016-04-25 08:02

MOT test number

688603173004

Result**✓ Passed****Advice**

Small cut outer sidewall on nearside front tyre

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8

2016-04-13 14:43

MOT test number

971256939364

Result**✗ Failed****Advice**

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #7

2015-04-13 08:40

MOT test number

737093405163

Result**✓ Passed**

**MOT #6** 2015-04-11 15:16**MOT test number** 238651705472**Result** ✗ Failed**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-04-04 11:18**MOT test number** 255424694063**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2014-03-29 09:29**MOT test number** 956098284085**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too far to the right (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-04-12 13:49**MOT test number** 367252303108**Result** ✓ Passed**MOT #2** 2012-04-20 12:42**MOT test number** 237011912497**Result** ✓ Passed



MOT #1	2011-04-05 10:37
MOT test number	155095091434
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 February 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CV08YMK
Plate since	2024-03-28
Current registration	 CV08YMK
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-04-24
Last registration	2024-01-12
Complete history	See info



Registration #1	2008-04-24	25 mi
Registration #2	2011-04-05	25.519 mi
Registration #3	2012-04-20	34.513 mi
Registration #4	2013-04-12	45.079 mi
Registration #5	2014-03-29	59.357 mi
Registration #6	2014-04-04	59.534 mi
Registration #7	2015-04-11	75.472 mi
Registration #8	2015-04-13	75.472 mi
Registration #9	2016-04-13	83.725 mi
Registration #10	2016-04-25	84.086 mi
Registration #11	2017-04-12	93.260 mi
Registration #12	2017-04-18	93.275 mi
Registration #13	2018-02-21	99.387 mi
Registration #14	2019-05-20	101.377 mi
Registration #15	2019-05-20	101.377 mi
Registration #16	2019-05-20	101.377 mi
Registration #17	2019-05-20	101.377 mi
Registration #18	2019-05-20	101.377 mi
Registration #19	2019-05-20	101.377 mi
Registration #20	2019-05-20	101.377 mi
Registration #21	2019-05-20	101.377 mi
Registration #22	2019-05-20	101.377 mi
Registration #23	2019-05-20	101.377 mi
Registration #24	2019-05-20	101.377 mi
Registration #25	2019-05-20	101.377 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141