




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB W/V 130TDI
Colour	Silver
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	16.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	219 g/km
CO2 label	K





MOT history

MOT expiry date	2024-01-04
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	48
Total items failed	25

MOT #21	2023-01-05 13:00
MOT test number	664599487480
Result	✓ Passed
Next expiry date	2024-01-04
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #20	2020-02-13 15:26
MOT test number	666088900623
Result	✓ Passed
Advice	O/s/f tyre close to legal limit
Advice	Chips in windscreen
Advice	Various steering and suspension dust covers deteriorated
Advice	Oil leak
Advice	Rear brake pads low

**MOT #19**

2020-02-13 14:35

MOT test number

398467847943

Result**✗ Failed**

- Advice** Rear brake pads low
- Advice** O/s/f tyre close to legal limit
- Advice** Chips in windscreen
- Advice** Various steering and suspension dust covers deteriorated
- Advice** Oil leak
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #18

2019-02-12 12:00

MOT test number

213360074914

Result**✓ Passed**

- Advice** Exhaust deteriorated
- Advice** N/s/f tyre close to legal limit
- Advice** Oil leak
- Advice** N/s/f bottom ball joint dust cover splitting
- Advice** Screw in n/s/r tyre
- Advice** O/s/f tyre on legal limit

MOT #17

2018-02-09 13:01

MOT test number

228916562232

Result**✓ Passed**

- Advice** Slight front brake imbalance

**MOT #16** 2018-02-07 10:54**MOT test number** 435565111319**Result** ✗ Failed**Advice** Slight front brake imbalance**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #15** 2017-02-17 09:56**MOT test number** 724023151380**Result** ✓ Passed**Advice** Child seat fitted in rear, rear belts not tested**MOT #14** 2017-02-16 12:32**MOT test number** 352815581721**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Child seat fitted in rear, rear belts not tested**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #13** 2016-02-18 11:00**MOT test number** 876854876704**Result** ✓ Passed**Advice** Exhaust deteriorated**Advice** Spare tyre on legal limit**Advice** All tyres close to legal limit**Advice** Child seats in rear, no seat belts tested

**MOT #12**

2016-02-17 12:32

MOT test number

965732986375

Result**✗ Failed****Fail** Nearside Headlamp aim too low (1.8)**Advice** Exhaust deteriorated**Advice** Spare tyre on legal limit**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' danglys from mirror (8.3.1e)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** All tyres close to legal limit**Advice** Child seats in rear, no seat belts tested**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #11**

2015-03-10 17:30

MOT test number

175509765083

Result**✓ Passed****Notice** Centre and rear exhaust box poor condition



MOT #10	2015-03-03 16:15
MOT test number	235122665040
Result	✗ Failed
Fail	Offside Inner Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
Pass with rectification	Nearside Headlamp aim too far to the right (1.8)
Fail	Nearside Inner Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
Fail	Nearside Seat belt retracting mechanism defective (5.2.5b)
Fail	Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Outer Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Notice	Centre and rear exhaust box poor condition

MOT #9	2014-03-20 16:51
MOT test number	178619874409
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-05-21 16:47**MOT test number** 138011743167**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Lower Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Rear exhaust corroded**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2013-05-20 10:48**MOT test number** 188170743153**Result** ✗ Failed**Fail** Front position lamp(s) not working (1.1.A.3b)**Notice** Rear exhaust corroded**Fail** Offside Front Headlamp aim too low (1.8)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Lower Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #6** 2012-05-15 11:40**MOT test number** 866066432139**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**MOT #5** 2012-05-15 11:40**MOT test number** 335236932192**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #4** 2011-05-19 10:49**MOT test number** 895509631172**Result** ✓ Passed**Notice** Front brake disc's wearing**Notice** Oil leak**MOT #3** 2010-05-12 12:35**MOT test number** 924072930147**Result** ✓ Passed**MOT #2** 2010-05-12 11:54**MOT test number** 254112530180**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #1** 2009-05-28 15:05**MOT test number** 533388549161**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✗
MOT

Expired:
4 January 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	4 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 T555TKD
Plate since	2024-03-29
Current registration	 T555TKD
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-14
Last registration	2023-01-05
Complete history	See info



Registration #1	2008-03-14	24 mi
Registration #2	2009-05-28	20.051 mi
Registration #3	2010-05-12	34.635 mi
Registration #4	2010-05-12	34.635 mi
Registration #5	2011-05-19	49.008 mi
Registration #6	2012-05-15	61.462 mi
Registration #7	2013-05-20	77.790 mi
Registration #8	2013-05-21	77.832 mi
Registration #9	2014-03-20	104.021 mi
Registration #10	2015-03-03	115.071 mi
Registration #11	2015-03-10	115.220 mi
Registration #12	2015-03-10	115.220 mi
Registration #13	2015-03-10	115.220 mi
Registration #14	2015-03-10	115.220 mi
Registration #15	2015-03-10	115.220 mi
Registration #16	2015-03-10	115.220 mi
Registration #17	2015-03-10	115.220 mi
Registration #18	2015-03-10	115.220 mi
Registration #19	2015-03-10	115.220 mi
Registration #20	2015-03-10	115.220 mi
Registration #21	2015-03-10	115.220 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	4890 mm
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	BNZ 095186