



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Grey
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 2

Date	2021-09-03
Pictures	38
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-12
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #12	2023-08-23 10:07
MOT test number	107871979452
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #11	2023-08-09 08:02
MOT test number	651510547428
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

MOT #10	2022-08-30 11:32
MOT test number	883317509264
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear facing bush. (5.3.4 (a) (i))

**MOT #9** 2022-08-23 09:58**MOT test number** 488975258152**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn Rear facing bush. (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear facing bush. (5.3.4 (a) (i))**Advice** Nearside Front Outer Tyre slightly damaged Sidewall. (5.2.3 (d) (ii))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #8** 2021-09-13 17:10**MOT test number** 239336815381**Result** ✓ Passed**MOT #7** 2021-03-22 18:16**MOT test number** 612194753569**Result** ✓ Passed**MOT #6** 2020-03-19 16:03**MOT test number** 854011700484**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #5** 2019-03-21 10:34**MOT test number** 281472737753**Result** ✓ Passed**MOT #4** 2018-03-16 12:40**MOT test number** 778559542602**Result** ✓ Passed



MOT #3	2017-03-21 16:50
MOT test number	416417218732
Result	✓ Passed

MOT #2	2016-03-14 13:10
MOT test number	728457304390
Result	✓ Passed

MOT #1	2015-03-13 10:11
MOT test number	349332775054
Result	✓ Passed

Advice Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	WJ12ZLE
Plate since	2019-09-29
Current registration	WJ12ZLE
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-16
Last registration	2023-08-23
Complete history	See info



Registration #1	2012-03-16	21 mi
Registration #2	2015-03-13	18.287 mi
Registration #3	2016-03-14	22.435 mi
Registration #4	2017-03-21	27.821 mi
Registration #5	2018-03-16	33.445 mi
Registration #6	2019-03-21	37.574 mi
Registration #7	2020-03-19	42.440 mi
Registration #8	2021-03-20	46.277 mi
Registration #9	2022-03-20	50.114 mi
Registration #10	2023-03-20	53.951 mi
Registration #11	2024-03-20	57.788 mi
Registration #12	2025-03-20	61.625 mi
Registration #13	2026-03-20	65.462 mi
Registration #14	2027-03-20	69.299 mi
Registration #15	2028-03-20	73.136 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867