




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





**Internet history**

**Entry 1**

Date	2021-02-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](http://autoonline.co.uk)



MOT history

MOT expiry date	2024-12-22
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	30
Total items failed	5

MOT #11	2023-11-26 10:56
MOT test number	288531109098
Result	✓ Passed
Next expiry date	2024-12-22
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))
<b>Advice</b>	Front and rear suspension components corroded
<b>Advice</b>	General underbody corrosion

MOT #10	2023-11-26 10:56
MOT test number	602920684832
Result	✗ Failed
<b>Pass with rectification</b>	Front Windscreen wiper not working (3.4 (a))
<b>Advice</b>	Front and rear suspension components corroded
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))
<b>Pass with rectification</b>	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Advice</b>	General underbody corrosion



**MOT #9** 2022-12-05 16:01

**MOT test number** 582200316850

**Result** ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge BOTH sides cutting edges (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2021-12-23 15:05

**MOT test number** 486437756501

**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2020-12-22 13:16

**MOT test number** 294446397385

**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #6** 2019-04-01 15:15

**MOT test number** 385913103061

**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))



MOT #5 2019-04-01 08:20

MOT test number 857899826060

Result ✗ Failed

**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MAJOR** Reversing lamp inoperative (4.6.1 (a))

**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2018-04-11 09:09

MOT test number 575763425444

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2017-04-01 10:24

MOT test number 621826865534

Result ✓ Passed

**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

**Advice** Rear Brake pad(s) wearing thin inner (3.5.1g)



**MOT #2** 2017-04-01 09:09

**MOT test number** 470781860962

**Result** ✗ Failed

**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

**Advice** Rear Brake pad(s) wearing thin inner (3.5.1g)

**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #1** 2016-04-07 07:00

**MOT test number** 965193678286

**Result** ✓ Passed

**Advice** Offside Front nail in tyre



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
22 December 2024

**Tax status** Valid until 1 February

**Days left** 279

**MOT expiry date** 22 December 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



**Finance check**

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-30
Last registration	2023-11-26
Complete history	<a href="#">See info</a>



Registration #1	2013-04-30	6 mi
Registration #2	2016-04-07	33.426 mi
Registration #3	2017-04-01	47.348 mi
Registration #4	2017-04-01	47.348 mi
Registration #5	2018-04-11	58.219 mi
Registration #6	2019-04-01	68.054 mi
Registration #7	2019-04-01	68.055 mi
Registration #8	2019-04-01	68.055 mi
Registration #9	2019-04-01	68.055 mi
Registration #10	2019-04-01	68.055 mi
Registration #11	2019-04-01	68.055 mi
Registration #12	2019-04-01	68.055 mi
Registration #13	2019-04-01	68.055 mi

[More info >](#)



## Safety ratings

<b>NCAP rating</b>	★★★★★
<b>Adult</b>	95%
<b>Children</b>	84%
<b>Pedestrian</b>	46%
<b>Safety systems</b>	71%
<b>Overall rating</b>	81%
<b>Video</b>	<a href="#">see crash video</a>



## Dimensions & weight

<b>Width</b>	2085 mm
<b>Height</b>	1761 mm
<b>Length</b>	4596 mm
<b>Wheel base</b>	2707 mm
<b>Kerb weight</b>	1836 kg
<b>Max. allowed weight</b>	2505 kg

## Additional information

<b>Fuel delivery</b>	Direct Injection
<b>Number of doors</b>	5
<b>Number of seats</b>	5
<b>Number of axles</b>	2
<b>Engine number</b>	Z22D1 263998K LNQ