





report date: 2024-03-29

### General information

Make	CITROEN
Model	XSARA HDI EXCLUSIVE EGS GRAND PICASSO
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
Gearbox	6 speed Semi-Automatic

# Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/12



# Internet history

### Entry 1

Date 2021-10-14

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2023-04-12
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #13	2022-04-13 15:41
MOT test number	355152996733
Result	✓ Passed
Next expiry date	2023-04-12

MOT #12		2021-07-07 11:57
MOT test	number	981593697676
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2020-07-22 10:25
MOT test number	796033510019
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT #10 2020-07-17 10:06

MOT test number 233939839571

**Result** X Failed

**Fail** Offside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

MOT #9 2019-04-10 12:32

**MOT test number** 989961070362

Result \( \sqrt{Passed} \)

**MOT #8** 2018-04-03 08:50

**MOT test number** 813557470905

Result \( \sqrt{Passed} \)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2018-04-03 08:50

MOT test number 856545262065

Result × Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)

**MOT #6** 2017-04-20 11:34

**MOT test number** 867794396355

CarCheck.co.uk page 4/12



MOT #5 2016-07-12 09:51

**MOT test number** 595194839304

**Result** ✓ Passed

MOT #4 2015-07-15 10:59

**MOT test number** 177886995129

**Result** ✓ Passed

MOT #3 2014-07-25 12:57

MOT test number 669236204255

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #2 2014-07-24 12:44

MOT test number 909925804200

**Result** X Failed

**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

**Notice** Child seat fitted not allowing full inspection of adult belt

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2013-06-26 11:10

**MOT test number** 825707673180

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



#### Tax & MOT check



X MOT

Tax expired: 1 July 2023 Expired: 12 April 2023

Tax status Expired at 1 July 2023

Days left 304 days too late
MOT expiry date 12 April 2023

Full MOT history See MOT history

### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full it	
**************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	NK SIN
Plate since	
	Mana info
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-08-04
Last registration	2022-04-13
Complete history	See info



Registration #1	2010-08-04	25 mi
Registration #2	2013-06-26	22.898 mi
Registration #3	2014-07-24	31.782 mi
Registration #4	2014-07-25	31.821 mi
Registration #5	2015-07-15	39.829 mi
Registration #6	2016-07-12	47.575 mi
Registration #7	2017-04-20	53.385 mi
Registration #8	2018-04-03	58.085 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



# Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1539 kg
Max. allowed weight	2250 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBBN0303660

CarCheck.co.uk page 12/12