



report date: 2024-03-28

## General information

Make	NISSAN
Model	ALMERA SE
Colour	Silver
Year of manufacture	2004
Top speed	110 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-30
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-28
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	61
Total items failed	11

MOT #25	2023-08-09 15:45
MOT test number	808382127869
Result	✓ Passed
Next expiry date	2024-08-28
Advice	Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR (1.1.14 (a) (ii))
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Gearbox mounting defective
Advice	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #24**

2023-08-08 11:29

**MOT test number**

806079199999

**Result****✗ Failed****Advice** Gearbox mounting defective**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #23**

2022-08-26 13:43

**MOT test number**

110969525149

**Result****✓ Passed****Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR (1.1.14 (a) (ii))**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #22**

2022-08-26 11:42

**MOT test number**

111759076377

**Result****✗ Failed****MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR (1.1.14 (a) (ii))**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #21**

2021-08-09 14:58

**MOT test number**

156020152730

**Result****✓ Passed****Advice** Exhaust system corroded**Advice** All brake discs corroded**MOT #20**

2021-08-09 14:58

**MOT test number**

250540850535

**Result****✗ Failed****Advice** Exhaust system corroded**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** All brake discs corroded**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

**MOT #19**

2020-08-29 14:52

**MOT test number**

251576890520

**Result**

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #18**

2020-08-29 14:52

**MOT test number**

277932992659

**Result**

✗ Failed

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17**

2019-06-08 11:43

**MOT test number**

507985261551

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2018-06-19 18:12**MOT test number** 921342651298**Result** ✓ Passed**Advice** Engine oil sump corroded.**MOT #15** 2018-06-19 18:12**MOT test number** 538405032893**Result** ✗ Failed**Advice** Engine oil sump corroded.**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #14** 2017-03-31 17:35**MOT test number** 903513725548**Result** ✓ Passed**MOT #13** 2016-03-15 18:06**MOT test number** 757588420323**Result** ✓ Passed**MOT #12** 2016-03-15 18:06**MOT test number** 915592248537**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #11** 2015-03-09 18:19**MOT test number** 375738465059**Result** ✓ Passed

**MOT #10** 2015-03-09 18:19**MOT test number** 545868165062**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #9** 2013-09-04 14:21**MOT test number** 856097343272**Result** ✓ Passed**Notice** Front inner pads look low**Advice** Nearside Inner Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2013-09-04 14:21**MOT test number** 578527543251**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Inner Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Front inner pads look low**MOT #7** 2012-09-20 08:47**MOT test number** 916874262269**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)





<b>MOT #6</b>	2011-09-29 09:49
<b>MOT test number</b>	168532971295
<b>Result</b>	✓ Passed
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

<b>MOT #5</b>	2010-09-24 15:29
<b>MOT test number</b>	320947460403
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
<b>Notice</b>	Slight oil leak from power steering rack
<b>Notice</b>	Offside front bumper damaged

<b>MOT #4</b>	2009-10-03 09:08
<b>MOT test number</b>	641136979246
<b>Result</b>	✓ Passed
<b>Notice</b>	Child seat fitted not allowing full inspection of adult belt
<b>Notice</b>	Nail in offside rear tyre

<b>MOT #3</b>	2008-10-04 09:46
<b>MOT test number</b>	934678478208
<b>Result</b>	✗ Failed
<b>Notice</b>	Offside rear tyre soft!
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Pass with rectification</b>	Nearside Headlamp aim too low (1.8)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2008-10-04 09:46
MOT test number	352048478241
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Offside rear tyre soft!
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2007-09-29 13:27
MOT test number	132902877256
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
26 April 2024

✓

MOT

Expires:  
28 August 2024

Tax status	Expired at 26 April 2024
Days left	4 days too late
MOT expiry date	28 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-09-24
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2004-09-24	29 mi
Registration #2	2007-09-29	14.390 mi
Registration #3	2008-10-04	23.577 mi
Registration #4	2009-10-03	31.750 mi
Registration #5	2010-09-24	41.249 mi
Registration #6	2011-09-29	43.584 mi
Registration #7	2012-09-20	50.874 mi
Registration #8	2013-09-04	72.364 mi
Registration #9	2015-03-09	80.532 mi
Registration #10	2016-03-15	87.316 mi
Registration #11	2016-03-15	87.316 mi
Registration #12	2017-03-31	92.894 mi
Registration #13	2018-03-31	95.316 mi
Registration #14	2018-03-31	95.316 mi
Registration #15	2018-03-31	95.316 mi
Registration #16	2018-03-31	95.316 mi
Registration #17	2018-03-31	95.316 mi
Registration #18	2018-03-31	95.316 mi
Registration #19	2018-03-31	95.316 mi
Registration #20	2018-03-31	95.316 mi
Registration #21	2018-03-31	95.316 mi
Registration #22	2018-03-31	95.316 mi
Registration #23	2018-03-31	95.316 mi
Registration #24	2018-03-31	95.316 mi

More info >





Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	267070