



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-16
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-19
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	19
Total items failed	8

MOT #16	2023-10-13 15:43
MOT test number	895574573577
Result	✓ Passed
Next expiry date	2024-10-19
Advice	Nearside Front top mount noise from lock to lock
Advice	Slight wear in some suspension bushes
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2023-10-13 11:36
MOT test number	221624680142
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Slight wear in some suspension bushes
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Nearside Front top mount noise from lock to lock

**MOT #14**

2022-10-17 08:52

MOT test number

398239764582

Result

✓ Passed

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #13**

2022-10-13 09:33

MOT test number

391762281506

Result

✗ Failed

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #12**

2021-10-20 08:50

MOT test number

778987396262

Result

✓ Passed

MOT #11

2021-10-19 09:17

MOT test number

753411516625

Result

✗ Failed

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2020-11-09 15:24**MOT test number** 316822043003**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both sides, o/s worse. (5.2.3 (e))**MOT #9** 2019-11-19 11:14**MOT test number** 332622967402**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides scored and corroding. (1.1.14 (a) (ii))**Advice** Rear exhaust mount corroded and broken off silencer.**MOT #8** 2018-11-27 11:16**MOT test number** 399386592983**Result** ✓ Passed**MOT #7** 2017-11-20 09:44**MOT test number** 439437168421**Result** ✓ Passed**MOT #6** 2016-11-04 10:19**MOT test number** 570622142108**Result** ✓ Passed**MOT #5** 2016-11-04 10:19**MOT test number** 540895169061**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #4	2015-11-18 10:22
---------------	------------------

MOT test number	938196062279
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #3	2014-11-28 13:40
---------------	------------------

MOT test number	265862034336
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-03-20 14:49
---------------	------------------

MOT test number	236219874051
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-03-16 10:29
---------------	------------------

MOT test number	808625473012
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-17
Last registration	2023-10-13
Complete history	See info



Registration #1	2010-03-17	18 mi
Registration #2	2013-03-16	39.176 mi
Registration #3	2014-03-20	47.103 mi
Registration #4	2014-11-28	52.101 mi
Registration #5	2015-11-18	63.430 mi
Registration #6	2016-11-04	75.072 mi
Registration #7	2016-11-04	75.072 mi
Registration #8	2017-11-20	87.974 mi
Registration #9	2018-11-27	97.871 mi
Registration #10	2019-11-27	107.768 mi
Registration #11	2020-11-27	117.665 mi
Registration #12	2021-11-27	127.562 mi
Registration #13	2022-11-27	137.459 mi
Registration #14	2023-10-13	147.356 mi
Registration #15	2023-10-13	147.356 mi
Registration #16	2023-10-13	147.356 mi
Registration #17	2023-10-13	147.356 mi
Registration #18	2023-10-13	147.356 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

AB89987