





report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2014
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

_		4		7
ᆮ	n	Т	rν	1

LIICI Y I	
Date	2021-02-05
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-08-15
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	5

MOT #9	2023-08-14 08:43
MOT test number	271686138598
Result	✓ Passed
Next expiry date	2024-08-15
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #8	2023-08-14 08:43	
MOT test number	288841377626	
Result	X Failed	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))		

CarCheck.co.uk page 3/12



Fail

KE14ZNH report date: 2024-03-29

MOT #7

MOT test number

Result

Advice
Oil leak, but not excessive (8.4.1 (a) (i))

Minor
Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6 2021-07-23 16:27 **MOT** test number 754056293324 Result ✓ Passed **MOT #5** 2020-08-11 09:45 355794214310 **MOT test number** Result Passed **MOT #4** 2019-08-09 15:17 **MOT** test number 535369913437 Result ✓ Passed **MOT** #3 2018-08-16 15:30 **MOT** test number 208881100295 Result ✓ Passed **MOT #2** 2018-08-16 11:56 **MOT** test number 133668218226

MOT test number

Result

Fail Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

Fail Offside Front Position lamp not working (4.2.1 (a))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #1 2017-08-09 08:16

MOT test number 633823682289

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category
Type

Damage 2

Category

Date

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



KE14ZNH

report date: 2024-03-29

More info >

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-31
Last registration	2023-08-14
Complete history	See info



Registration #1	2014-07-31	14 mi
Registration #2	2017-08-09	34.250 mi
Registration #3	2018-08-16	145.742 mi
Registration #4	2018-08-16	45.742 mi
Registration #5	2019-08-09	57.062 mi
Registration #6	2020-08-11	63.208 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		19.397-es

More info >

CarCheck.co.uk page 11/12



Additional information

Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats	2	
Engine number	263A20005566978 LN9	

CarCheck.co.uk page 12/12