



General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 2


Date	2021-12-10
Pictures	37
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-01
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-05
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	31
Total items failed	13

MOT #19	2023-11-06 10:56
MOT test number	541488626080
Result	✓ Passed
Next expiry date	2024-11-05
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-11-06 10:56
MOT test number	137686165106
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #17** 2022-10-31 16:38**MOT test number** 461880342200**Result** ✓ Passed**MOT #16** 2022-10-31 10:10**MOT test number** 130468107587**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #15** 2021-10-30 08:42**MOT test number** 345973889969**Result** ✓ Passed**Advice** UNDER TRAYS FITTED**MOT #14** 2020-11-04 12:52**MOT test number** 926500568759**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2020-11-04 11:55**MOT test number** 939660143638**Result** ✗ Failed**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2019-10-10 12:17**MOT test number** 242264620967**Result** ✓ Passed**Advice** Front brake discs in poor condition**Advice** Osf tyre wearing on edge**Advice** Rear brake discs pitted on edge**MOT #11** 2019-10-08 15:34**MOT test number** 782801330310**Result** ✗ Failed**Advice** Rear brake discs pitted on edge**Advice** Front brake discs in poor condition**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Osf tyre wearing on edge**MOT #10** 2018-12-11 13:01**MOT test number** 976951494727**Result** ✓ Passed**Advice** Front Inner Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**Advice** Front Items removed from driver's view prior to test**Advice** Sill covers and undertrays fitted**Advice** Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

**MOT #9** 2017-12-21 08:24**MOT test number** 968902045474**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)

**MOT #8** 2017-12-18 13:20**MOT test number** 737157224688**Result** ✗ Failed

- Fail** Nearside Front Headlamp aim too low (1.8)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Front Track rod end ball joint has slight play both (2.2.B.1f)
- Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)
- Fail** Offside Front Headlamp aim too low (1.8)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #7** 2016-12-20 14:54**MOT test number** 741640311843**Result** ✓ Passed

**MOT #6** 2016-09-05 13:27**MOT test number** 290512870170**Result** ✓ Passed**MOT #5** 2016-08-31 10:45**MOT test number** 289527209099**Result** ✗ Failed**Fail** Rear Trailer electrical socket insecure (1.9.3a)**Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2015-09-01 08:32**MOT test number** 329234345221**Result** ✓ Passed**MOT #3** 2014-09-01 17:26**MOT test number** 136094844270**Result** ✓ Passed**MOT #2** 2014-09-01 14:49**MOT test number** 588594944219**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #1** 2013-09-02 15:30**MOT test number** 319075943256**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
5 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	5 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-09-01
Last registration	2023-11-06
Complete history	<a href="#">See info</a>



Registration #1	2010-09-01	19 mi
Registration #2	2013-09-02	29.518 mi
Registration #3	2014-09-01	42.041 mi
Registration #4	2014-09-01	42.041 mi
Registration #5	2015-09-01	53.582 mi
Registration #6	2016-08-31	66.209 mi
Registration #7	2016-09-05	66.283 mi
Registration #8	2016-12-20	69.996 mi
Registration #9	2017-12-18	80.610 mi
Registration #10	2017-12-21	80.611 mi
Registration #11	2018-12-11	86.965 mi
Registration #12	2019-05-29	91.377 mi
Registration #13	2019-05-29	91.377 mi
Registration #14	2019-05-29	91.377 mi
Registration #15	2019-05-29	91.377 mi
Registration #16	2019-05-29	91.377 mi
Registration #17	2019-05-29	91.377 mi
Registration #18	2019-05-29	91.377 mi
Registration #19	2019-05-29	91.377 mi
Registration #20	2019-05-29	91.377 mi
Registration #21	2019-05-29	91.377 mi
Registration #22	2019-05-29	91.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2238 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYWS4031926