




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 2700 L1H1 CDTI P/V
Colour	White
Year of manufacture	2016
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-13
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #7 2023-08-12 09:24

MOT test number 224618856299

Result ✔ Passed

Next expiry date 2024-08-13

- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front + rear (1.1.14 (a) (ii))
- Advice** Under-trays/Engine cover fitted obscuring view of some components
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6 2023-08-05 08:52

MOT test number 509081173813

Result ✘ Failed

- MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Under-trays/Engine cover fitted obscuring view of some components
- MAJOR** Front Track rod end ball joint has excessive play Nearside + Offside (2.1.3 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front + rear (1.1.14 (a) (ii))



MOT #5	2022-08-06 08:47
MOT test number	602360129601
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively Nearside + Offside small lip (1.1.14 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge Nearside + Offside (5.2.3 (e))

MOT #4	2021-08-14 10:06
MOT test number	833901478375
Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2021-06-02 06:44
MOT test number	983989896782
Result	✓ Passed

MOT #2	2020-06-22 15:43
MOT test number	251886299291
Result	✓ Passed

MOT #1	2019-06-17 08:23
MOT test number	148829191612
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
13 August 2024

Tax status Valid until 1 August

Days left 95

MOT expiry date 13 August 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-30
Last registration	2023-08-12
Complete history	See info



Registration #1	2016-06-30	11 mi
Registration #2	2019-06-17	21.684 mi
Registration #3	2020-06-22	26.539 mi
Registration #4	2021-06-02	32.398 mi
Registration #5	2022-06-02	32.398 mi
Registration #6	2022-06-02	32.398 mi
Registration #7	2022-06-02	32.398 mi
Registration #8	2022-06-02	32.398 mi
Registration #9	2023-08-12	32.398 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	1956 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1661 kg
Max. allowed weight	2740 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	R9M MD - C101589LWZ