





report date: 2024-03-29

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Black
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-03

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-02
Pictures	40

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-29
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	24
Total items failed	4

MOT #17		2023-06-29 13:51
MOT test	number	559180567509
Result		✓ Passed
Next exp	iry date	2024-06-29
Minor Nearside Rear Suspension rod ball joint dust cover severely deteriorated tie rod (5.3.4 (b) (i))		
Minor Offside Rear Suspension rod ball joint dust cover severely deteriorated tie rod (5.3.4 (b) (i))		

MOT #16	2022-06-20 10:28
MOT test number	286861097641
Result	✓ Passed
MOT #15	2021-06-30 12:13
MOT test number	713522067900
Result	✓ Passed
MOT #14	2020-09-07 12:57
MOT test number	703834332793
Result	✓ Passed

MOT #13	2019-10-12 12:37
MOT test number	951477536627
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2018-09-05 14:55 **MOT** test number 137721559400 ✓ Passed Result **MOT #11** 2017-08-08 08:07 **MOT test number** 752934906335 Result ✓ Passed Rear Brake pad(s) wearing thin (3.5.1g) Advice Advice Front Shock absorber has a light misting of oil both {slight] (2.7.3)

Brake disc worn, pitted or scored, but not seriously weakened all (3.5.1i)

Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement

both sides (2.4.G.2)

Advice

Advice

Advice Rear Lower Shock absorber has a slightly worn bush both (2.7.4)

MOT #10

MOT test number

806727009120

Result

Advice
Rear Lower Suspension arm has slight play in a pin/bush both sides outer (2.4.G.2)

Advice
Front Shock absorber has a light misting of oil both sides weeping (2.7.3)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9 2015-12-16 12:37 261275832790 **MOT** test number ✓ Passed Result **Advice** Nearside Front TYRE HAS CRACKS IN SIDE WALLS NOT DEEP ENOUGH TO REACH CORDS Advice Nearside Front Valve stem slightly damaged (4.1.D.1e) Advice Offside Rear Valve stem slightly damaged (4.1.D.1e) Advice Nearside Front position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)Advice Nearside Rear TYRE HAS CRACKS IN SIDE WALLS NOT DEEP ENOUGH TO REACH CORDS Advice Offside Rear HAS CRACKS IN SIDE WALLS NOT DEEP ENOUGH TO REACH CORDS Advice Nearside Rear Valve stem slightly damaged (4.1.D.1e) Advice Offside Front Valve stem slightly damaged (4.1.D.1e) Advice Offside Front Front position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)Advice Offside Front TYRE HAS CRACKS IN SIDE WALLS NOT DEEP ENOUFGH TO REACH CORDS

MOT #8	2015-04-08 10:41
MOT test number	487878295097
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #7		2015-04-08 10:41
MOT test number		775578995004
Result		🗙 Failed
Pass with rectification	Rear registration plate character(s) incorrectly spaced (6.3.4a)	
Pass with rectification	Front registration plate character(s) incorrectly spaced (6.3.4a)	
Advice Front Brake pad(s) wearing thin (3.5.1g)		

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #6 2014-04-04 14:12

MOT test number 127714294438

Result ✓ Passed

MOT #5 2014-04-04 14:12

MOT test number 388764594026

Result X Failed

Pass with rectification Rear registration plate character(s) incorrectly spaced (6.3.4a)

Pass with rectification Front registration plate character(s) incorrectly spaced (6.3.4a)

MOT #4 2013-03-25 15:08

MOT test number 365844083058

Result \rightarrow Passed

MOT #3 2011-04-15 18:28

MOT test number 279715701441

MOT #2 2010-04-13 12:43

MOT test number 543323700193

Result ✓ Passed

Notice N/s/f & n/s/r tyre outer wall damaged

Advice Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1 2009-11-05 13:20

MOT test number 484559809408

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	history

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	UK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-11-03
Last registration	2023-06-29
Complete history	See info



Registration #1	2006-11-03	13 mi
Registration #2	2009-11-05	48.156 mi
Registration #3	2010-04-13	49.255 mi
Registration #4	2011-04-15	53.448 mi
Registration #5	2013-03-25	61.690 mi
Registration #6	2014-04-04	68.938 mi
Registration #7	2015-04-08	76.198 mi
Registration #8	2015-12-16	79.101 mi
Registration #9	2016-12-01	85.378 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 au

More info >

CarCheck.co.uk page 12/13



WK56ZVY report date: 2024-03-29

			_		
- 11	manc	Innc	. .	MOL	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G

CarCheck.co.uk page 13/13