



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	VITO 109 CDI LONG P/V
Colour	White
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	240 Nm at 1.400 rpm
Cylinders	4
Fuel type	Diesel





Internet history

Entry 1

Date	2021-11-06
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #16	2021-10-12 14:03
MOT test number	848637292137
Result	✓ Passed
Next expiry date	2022-10-11

MOT #15	2021-10-11 11:04
MOT test number	872409109886
Result	✗ Failed
Fail	Front Brake lever has insufficient reserve travel (1.1.2 (a))
Fail	Offside Front Headlamp are incorrectly positioned (4.1.4 (a))
Fail	Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #14	2020-10-12 15:36
MOT test number	467211986529
Result	✓ Passed

MOT #13	2019-10-04 18:11
MOT test number	531253159248
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2018-09-29 18:03
MOT test number	897680110301
Result	✓ Passed

MOT #11	2017-10-03 18:12
MOT test number	605050389482
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #10 2016-09-27 13:20

MOT test number 749307312163

Result ✓ Passed

MOT #9 2015-10-31 10:46

MOT test number 917502710718

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2014-10-31 10:36

MOT test number 697084904386

Result ✓ Passed

MOT #7 2013-10-28 20:53

MOT test number 499991803347

Result ✓ Passed

Notice Nsr tyre wearing on inner edge

MOT #6 2013-10-22 13:48

MOT test number 828105493217

Result ✗ Failed

Fail Offside Rear coil spring broken (2.4.C.1a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Notice Nsr tyre wearing on inner edge

MOT #5 2012-10-09 09:20

MOT test number 379653882223

Result ✓ Passed



MOT #4 2012-10-08 08:58

MOT test number 756072682250

Result ✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Rear registration plate insecure (6.3.1b)
- Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)
- Fail** Offside Front Headlamp insecure (1.7.3)
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Front registration plate deteriorated (6.3.1d)
- Fail** Rear Parking brake lever has no reserve travel (3.1.6b)

MOT #3 2011-09-27 09:32

MOT test number 447910571291

Result ✓ Passed

MOT #2 2010-10-12 09:41

MOT test number 714535280207

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2009-10-08 14:53

MOT test number 510511189256

Result ✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	KF56DSX
Plate since	2019-03-29
Current registration	KF56DSX
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-10-18
Last registration	2021-10-12
Complete history	See info



Registration #1	2006-10-18	27 mi
Registration #2	2009-10-08	38.425 mi
Registration #3	2010-10-12	51.551 mi
Registration #4	2011-09-27	64.173 mi
Registration #5	2012-10-08	88.298 mi
Registration #6	2012-10-09	88.298 mi
Registration #7	2013-10-22	106.512 mi
Registration #8	2013-10-28	106.512 mi
Registration #9	2014-10-31	115.825 mi
Registration #10	2015-10-01	115.825 mi
Registration #11	2015-10-01	115.825 mi
Registration #12	2015-10-01	115.825 mi
Registration #13	2015-10-01	115.825 mi
Registration #14	2015-10-01	115.825 mi
Registration #15	2015-10-01	115.825 mi
Registration #16	2015-10-01	115.825 mi
Registration #17	2015-10-01	115.825 mi
Registration #18	2015-10-01	115.825 mi

[More info >](#)



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	64698350216006