





report date: 2024-03-29

#### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Grey
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/15



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-06-28

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

## MOT history

MOT expiry date	2024-03-30
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	29
Total items failed	22

MOT #19		2023-03-31 12:06
MOT test	number	332967079884
Result		✓ Passed
Next exp	iry date	2024-03-30
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Exhaust has a minor leak of exhaust gases system corroded (6.1.2 (a))	
<b>Advice</b> (5.3.2 (b))	Rear Shock absorbers has slight external damage to the casing both sides or	uter casing corroded
Advice	Under vehicle + all steering / suspension components corroded	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sid	es (1.1.14 (a) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view stone ch	ips (3.2 (a) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice	Brake hose has slight corrosion to ferrule all visible (1.1.12 (f) (i))	
Advice	Coil spring corroded all visible (5.3.1 (b) (i))	
Advice	Covers+ shields fitted	
Advice	Central heat shield loose but secure	
<b>Advice</b> (1.1.14 (a	Rear Brake disc worn, pitted or scored, but not seriously weakened both side	es heavily worn
<b>Minor</b> (4.7.1 (b)	Nearside Rear Registration plate lamp inoperative in the case of multiple lam (i))	ps or light sources

CarCheck.co.uk page 3/15



report date: 2024-03-29

**MOT #18** 2022-03-22 14:30 756217982683 **MOT** test number Result ✓ Passed **Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i)) **Advice** Covers + shields fitted **Advice** Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii)) Advice Front Inner Tyre worn close to legal limit/worn on edge both sides - perishing / cracking (5.2.3 (e)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) Minor Front Windscreen damaged but not adversely affecting driver's view stone chips (3.2 (a) (i))

**MOT #17** 2021-01-26 14:27 **MOT** test number 961977343922 Result Passed **MOT #16** 2021-01-26 06:39 **MOT test number** 870155670878 Result × Failed Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #15	2020-01-24 11:19
MOT test number	655138904395
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT test number

492204939806

Result

Fail Stop lamp(s) all not working (4.3.1 (a) (iii))

Fail Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MOT #13

MOT test number

909487648751

Result

✓ Passed

**MOT #12** 2019-01-10 16:16 **MOT** test number 631711130034 Result × Failed Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c)) Fail Windscreen wiper not working (3.4 (a)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #11
 2018-01-03 09:04

 MOT test number
 220224650212

 Result
 ✓ Passed

CarCheck.co.uk page 5/15



Result

Fail

YA08VWR

report date: 2024-03-29

× Failed

MOT #10 2018-01-03 06:31

**MOT test number** 942963751589

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

Rear brake excessively fluctuating both (3.7.B.3)

**MOT #9** 2017-01-06 07:20

**MOT test number** 963391492075

**Result** ✓ Passed

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2015-12-09 11:48

MOT test number 270321530616

**Result** ✓ Passed

**MOT #7** 2015-12-09 09:59

MOT test number 754549990228

**Result** X Failed

**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

**Fail** Nearside Stop lamp not working (1.2.1b)

MOT #6 2014-11-22 11:22

**MOT test number** 459186124310

CarCheck.co.uk page 6/15



report date: 2024-03-29

**MOT #5** 2014-11-21 10:06

**MOT test number** 375485624378

**Result** X Failed

Fail Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**Fail** Nearside Steering system has excessive free play detected at the steering wheel (steering rack fitted) (2.2.A.1b)

**Notice** Nail in nearside rear tyre

**Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)

MOT #4 2013-11-25 15:59

**MOT test number** 866659923383

**Result** ✓ Passed

**Advice** Nearside Ball joint has slight play (2.2.B.1f)

MOT #3 2013-11-25 10:09

MOT test number 346879723391

**Result** X Failed

Fail Offside Stop lamp not working (1.2.1b)

**Advice** Nearside Ball joint has slight play (2.2.B.1f)

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2012-11-28 10:16

**MOT test number** 675953732326

**Notice** Nail in nearside rear tyre

**Notice** Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #1

MOT test number

276829631334

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 8/15



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	30 March 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-08-21
Last registration	2023-03-31
Complete history	See info



Registration #1	2008-08-21	24 mi
Registration #2	2011-12-05	32.345 mi
Registration #3	2012-11-28	42.864 mi
Registration #4	2013-11-25	78.070 mi
Registration #5	2013-11-25	78.070 mi
Registration #6	2014-11-21	62.273 mi
Registration #7	2014-11-22	62.273 mi
Registration #8	2015-12-09	69.259 mi
Registration #9	2015-12-09	69.259 mi
Registration #10	2017-01-06	77.662 mi
Registration #11	2018-01-03	86.788 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 14/15



YA08VWR
report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1699 mm
Height	1420 mm
Length	4129 mm
Wheel base	2625 mm
Kerb weight	1175 kg
Max. allowed weight	1725 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15

Number of axles 2
Engine number D167628