

Ford



General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Blue
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G







Internet history

Entry	1

Date Pictures 2021-09-15

Listing price

View report

20



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	26
Total items failed	6

MOT #13	2024-03-22 13:07
MOT test number	661035393945
Result	✓ Passed
Next expiry date	2025-03-21

MOT #12		2023-03-21 16:24
MOT test	number	773633105142
Result		✓ Passed
Advice bushes bo	Rear Suspension arm pin or bush worn but not resulting in excessive moveme th sides (5.3.4 (a) (i))	ent trailing arm
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorate	ted (6.1.7 (g) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

MOT #11	2022-01-14 13:56
MOT test number	146120541479
Result	✓ Passed





MOT #10		2021-01-19 12:04
MOT test	number	121274638226
Result		✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing Both sides. (5.2.3 (d) (ii))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both sides.	(1.1.14 (a) (ii))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

МОТ #9	2020-01-02 12:02
MOT test number	618146330468
Result	✓ Passed

МОТ #8	2018-12-17 11:42
MOT test number	848372295576
Result	✓ Passed
MOT #7	2017-12-21 12:33
MOT test number	180089014694
Result	✓ Passed





MOT #6		2017-01-24 17:03
MOT test	number	376251004116
Result		✓ Passed
Advice	Under trays fitted obscuring underside components	
Advice (3.5.1i)	Rear brake disc worn, pitted or scored, but not seriously weakened both sides sl	ightly lipped
Advice	Front wiper blades slightly worn	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.	1a)

MOT #5	2017-01-23 15:21
MOT test number	139456680169
Result	🗙 Failed
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail Offside Front Inner Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Front wiper blades slightly worn	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened both sid (3.5.1i)	es slightly lipped
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A'	(8.3.1a)
Advice Under trays fitted obscuring underside components	

MOT #4		2016-01-13 10:02
MOT test	number	674116219074
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Front suspension has slight play in a lower suspension ball joint (2.5	5.B.1a)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)
Advice	Offside Front Windscreen has damage to an area less than a 40mm circle outside	e zone 'A' (8.3.1d)





MOT #3	2015-01-16 16:36
MOT test number	396086015044
Result	✓ Passed
MOT #2	2015-01-16 13:26
MOT test number	918726215036
Result	× Failed
Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Inner Front Brake pad(s) wearing thin (3.5.1g)	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Offside Inner Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #1		2013-10-08 11:26
MOT test	number	445421483267
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	



VK60TFX report date: 2024-03-28

Tax & MOT check

✓ Taxe	d	Expires:	✓ мот
1 October 2024		21 March 2025	Valid wetil 1 Ostabar
Tax status Days left			Valid until 1 October 155
MOT expiry date			21 March 2025
Full MOT history			<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-12
Last registration	2024-03-22
Complete history	See info



Registration #1	2010-10-12	6 mi
Registration #2	2013-10-08	52.466 mi
Registration #3	2015-01-16	74.402 mi
Registration #4	2015-01-16	74.402 mi
Registration #5	2016-01-13	95.282 mi
Registration #6	2017-01-23	108.542 mi
Registration #7	2017-01-24	108.542 mi
Registration #8	2017-12-21	120.931 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

Number of axles

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2154 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1733 kg
Max. allowed weight	2505 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

2