





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|----------------|
| Model | FOCUS ST-2 |
| Colour | Blue |
| Year of manufacture | 2010 |
| Top speed | 150 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 223 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 4.000 rpm |
| Engine capacity | 2.521 cc |
| Cylinders | 5 |
| Fuel type | Petrol |
| Consumption city | 20.5 mpg |
| Consumption extra urban | 41.5 mpg |
| Consumption combined | 30.4 mpg |
| CO2 emission | 224 g/km |
| CO2 label | K |



CarCheck.co.uk page 1/11



MOT history

| MOT expire date | 2023-08-24 |
|--------------------|------------|
| MOT expiry date | 2023-06-24 |
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 11 |
| Total items failed | 5 |

| MOT #13 | | 2022-08-25 16:52 |
|-----------|--|------------------|
| MOT test | number | 801240912225 |
| Result | | ✓ Passed |
| Next expi | ry date | 2023-08-24 |
| Advice | Offside Rear quarter panel damaged | |
| Advice | Offside Front bumper damaged | |
| Advice | Offside Rear Bumper mountings corroded but not likely to become detached | |

| MOT #12 | 2021-02-09 16:38 |
|----------|--|
| MOT test | number 544238843052 |
| Result | ✓ Passed |
| Advice | Offside Rear quarter panel damaged |
| Advice | Offside Front bumper damaged |
| Advice | Offside Rear Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i)) |

| MOT #11 | 2020-02-05 15:19 |
|-----------------|------------------|
| MOT test number | 788374821758 |
| Result | ✓ Passed |

CarCheck.co.uk page 2/11



MOT #10 2019-01-28 11:33

MOT test number 233309569099

Result ✓ Passed

MOT #9 2019-01-28 11:33

MOT test number 194334550433

Result × Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

MOT #8 2018-02-07 11:13

MOT test number 720728482789

Result ✓ Passed

MOT #7 2018-02-05 16:47

MOT test number 458746461216

Result ★ Failed

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #6 2017-01-09 16:29

MOT test number 413562505443

Advice Offside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #5 2017-01-09 09:56

MOT test number 367894889996

Result X Failed

Advice Offside Rear Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

Fail Offside Front Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

CarCheck.co.uk page 3/11



MOT #4 2016-01-07 11:31 214855975068 **MOT** test number Result ✓ Passed **MOT** #3 2016-01-07 11:31 **MOT test number** 125927275163 Result × Failed Pass with rectification Offside Headlamp aim too low (1.8) Pass with rectification Nearside Headlamp aim too low (1.8)

MOT #2

MOT test number

156795115017

Result

Advice (2.4.G.2)

Notice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

 MOT #1
 2014-01-10 16:09

 MOT test number
 198920914441

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax expired: 30 November 2021

X MOT

Expired: 24 August 2023

| Tax status | Expired at 30 November 2021 |
|------------------|-----------------------------|
| Days left | 881 days too late |
| MOT expiry date | 24 August 2023 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner mistory | |
|--|-------------|
| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | NIA AIN |
| Plate since | m.o.o |
| Current registration | NK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2010-03-27 |
| Last registration | 2022-08-25 |
| Complete history | See info |



| Registration #1 | 2010-03-27 | 28 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-01-10 | 36.035 mi |
| Registration #3 | 2015-01-15 | 50.835 mi |
| Registration #4 | 2016-01-07 | 62.027 mi |
| Registration #5 | 2016-01-07 | 62.027 mi |
| Registration #6 | 2017-01-09 | 76.556 mi |
| Registration #7 | 2017-01-09 | 76.556 mi |
| Registration #8 | | 77.777 46 |
| Registration #9 | | 11.777 es |
| Registration #10 | | 77.777 46 |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1839 mm |
|---------------------|---------|
| Height | 1497 mm |
| Length | 4357 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1392 kg |
| Max. allowed weight | 1860 kg |

Additional information

| Fuel tank capacity | 55 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles 2

Engine number AS79185