



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Blue
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-04
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	16
Total items failed	2

MOT #17	2023-10-06 08:33
MOT test number	756322425646
Result	✓ Passed
Next expiry date	2024-10-05

MOT #16	2022-10-05 12:31
MOT test number	855505226161
Result	✓ Passed

MOT #15	2022-10-05 12:30
MOT test number	372032984343
Result	✗ Failed
Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #14	2022-05-23 12:16
MOT test number	530808978143
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge wear (5.2.3 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush tearing (5.3.4 (a) (i))	
Advice O/s/f abs wire lose	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush tearing (5.3.4 (a) (i))	

**MOT #13**

2022-05-20 12:44

MOT test number

438204558526

Result**✗ Failed****MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush tearing (5.3.4 (a) (i))**MAJOR** Exhaust has a major leak of exhaust gases front flexi (6.1.2 (a))**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush tearing (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge wear (5.2.3 (e))**Advice** O/s/f abs wire lose**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #12**

2021-05-14 14:07

MOT test number

927229778777

Result**✓ Passed****MOT #11**

2020-05-26 12:41

MOT test number

585006959328

Result**✓ Passed****Advice** Exhaust front pipe slight deterioration**Advice** Nearside Rear tyre cracked and perished in tread area**Advice** Some corrosion to suspension components**MOT #10**

2019-04-10 08:01

MOT test number

943365117579

Result**✓ Passed**



MOT #9	2018-04-06 12:14
---------------	------------------

MOT test number	300670491570
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2017-04-29 09:32
---------------	------------------

MOT test number	168257016280
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2017-04-29 09:32
---------------	------------------

MOT test number	468460320454
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Front coil spring broken (2.4.C.1a)
--------------------------------	---

MOT #6	2016-10-12 09:20
---------------	------------------

MOT test number	875398259327
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-10-05 09:05
---------------	------------------

MOT test number	969122604759
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-10-02 10:30
---------------	------------------

MOT test number	298005074216
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-09-25 14:02
---------------	------------------

MOT test number	536208563231
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #2	2012-10-10 11:28
MOT test number	239374182250
Result	✓ Passed

MOT #1	2011-10-11 15:24
MOT test number	736274481200
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	PE58RZK
Plate since	2019-06-29
Current registration	PE58RZK
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-23
Last registration	2023-10-06
Complete history	See info



Registration #1	2008-10-23	18 mi
Registration #2	2011-10-11	13.771 mi
Registration #3	2012-10-10	17.573 mi
Registration #4	2013-09-25	20.040 mi
Registration #5	2014-10-02	23.661 mi
Registration #6	2015-10-05	26.918 mi
Registration #7	2016-10-12	30.164 mi
Registration #8	2017-04-29	30.921 mi
Registration #9	2017-04-29	30.921 mi
Registration #10	2018-04-06	40.782 mi
Registration #11	2019-04-06	50.643 mi
Registration #12	2020-04-06	60.504 mi
Registration #13	2021-04-06	70.365 mi
Registration #14	2022-04-06	80.226 mi
Registration #15	2023-04-06	90.087 mi
Registration #16	2024-04-06	100.000 mi
Registration #17	2025-04-06	110.000 mi
Registration #18	2026-04-06	120.000 mi
Registration #19	2027-04-06	130.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141