



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H2 P/V CDTi
Colour	White
Year of manufacture	2012
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	285 Nm at 1.250 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.0 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-31
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-05
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	20
Total items failed	9

MOT #13	2023-07-20 14:57
MOT test number	558711791743
Result	✓ Passed
Next expiry date	2024-08-05

MOT #12	2023-07-19 15:18
MOT test number	521853491514
Result	✗ Failed
Fail	Nearside Front Additional braking device mounting insecure and functionality of device affected brake caliper mounig bolt loose (1.1.19 (a) (ii))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #11	2022-07-21 14:48
MOT test number	515639350731
Result	✓ Passed

**MOT #10**

2022-07-13 13:19

**MOT test number**

766809705679

**Result****✗ Failed**

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Seat belt buckle damaged (7.1.2 (d))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #9**

2021-08-06 15:17

**MOT test number**

962871650028

**Result****✓ Passed**

- Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))
- Advice** Rear four seats and belts fitted and tested at test
- Advice** Nearside Rear Inner Seat belt buckle slightly damaged (7.1.2 (d))

**MOT #8**

2021-08-06 15:17

**MOT test number**

385248262196

**Result****✗ Failed**

- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Pass with rectification** Front Headlamp aim too low both sides (4.1.2 (a))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))
- Advice** Nearside Rear Inner Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Rear four seats and belts fitted and tested at test

**MOT #7**

2020-05-26 09:29

**MOT test number**

330854294017

**Result**

✓ Passed

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6**

2019-05-29 12:46

**MOT test number**

473736409007

**Result**

✓ Passed

**Advice** Brake disc worn, but not excessively All (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5**

2019-05-29 10:30

**MOT test number**

521771142927

**Result**

✗ Failed

**Advice** Brake pedal slightly soft**Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake disc worn, but not excessively All (1.1.14 (a) (i))



MOT #4	2018-05-15 10:26
MOT test number	109846204950
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit both (4.1.E.1)

MOT #3	2017-04-25 10:47
MOT test number	299864349651
Result	✓ Passed

MOT #2	2016-05-23 14:12
MOT test number	916758749147
Result	✓ Passed

MOT #1	2015-03-16 12:50
MOT test number	556855075082
Result	✓ Passed



Tax & MOT check

✓  
Taxed

Tax due:  
1 August 2024

✓  
MOT

Expires:  
5 August 2024

Tax status

Valid until 1 August

Days left

94

MOT expiry date

5 August 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-27
Last registration	2023-07-20
Complete history	<a href="#">See info</a>



Registration #1	2012-03-27	10 mi
Registration #2	2015-03-16	17.780 mi
Registration #3	2016-05-23	24.483 mi
Registration #4	2017-04-25	49.540 mi
Registration #5	2018-05-15	67.865 mi
Registration #6	2019-05-29	90.090 mi
Registration #7	2019-05-29	90.093 mi
Registration #8	2020-05-26	99.454 mi
Registration #9	2020-05-26	99.454 mi
Registration #10	2020-05-26	99.454 mi
Registration #11	2020-05-26	99.454 mi
Registration #12	2020-05-26	99.454 mi
Registration #13	2020-05-26	99.454 mi
Registration #14	2020-05-26	99.454 mi
Registration #15	2020-05-26	99.454 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	78%
Pedestrian	41%
Safety systems	86%
Overall rating	75%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	5548 mm
Kerb weight	1890 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C036631