



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ3 DDIS
Colour	Silver
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-04-07
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #12	2023-04-04 10:42
MOT test number	113873258664
Result	✓ Passed
Next expiry date	2024-04-07
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11	2022-04-06 14:28
MOT test number	967960814336
Result	✓ Passed
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material all metal brake pipes (1.1.11 (c))

**MOT #10**

2022-04-06 07:40

**MOT test number**

524853433870

**Result****✗ Failed**

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material all metal brake pipes (1.1.11 (c))

**MOT #9**

2021-03-10 15:58

**MOT test number**

638228777804

**Result****✓ Passed****MOT #8**

2021-03-05 13:42

**MOT test number**

703854078369

**Result****✗ Failed**

- Fail** Exhaust has a major leak of exhaust gases back box (6.1.2 (a))

**MOT #7**

2020-03-16 11:02

**MOT test number**

452629785208

**Result****✓ Passed**

**MOT #6** 2019-03-15 11:55**MOT test number** 331013447396**Result** ✓ Passed**Advice** Brake pipes greased all round**MOT #5** 2018-03-29 16:13**MOT test number** 281734071900**Result** ✓ Passed**MOT #4** 2018-03-29 09:05**MOT test number** 871419505594**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Rear Tyre worn close to the legal limit wearing on inner edge (4.1.E.1)**MOT #3** 2017-03-28 12:46**MOT test number** 479336040152**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded pipe from front to rear (3.6.B.2c)**MOT #2** 2016-03-24 11:29**MOT test number** 441862989573**Result** ✓ Passed**MOT #1** 2015-04-08 18:00**MOT test number** 347808095080**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 January 2025

✗  
**MOT**  
  
Expired:  
7 April 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	7 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>SK12ZWV</b>
Plate since	2019-03-29
Current registration	<b>SK12ZWV</b>
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-28
Last registration	2023-04-04
Complete history	<a href="#">See info</a>



Registration #1	2012-03-28	29 mi
Registration #2	2015-04-08	30.146 mi
Registration #3	2016-03-24	39.568 mi
Registration #4	2017-03-28	49.966 mi
Registration #5	2018-03-29	58.375 mi
Registration #6	2018-03-29	58.380 mi
Registration #7	2019-03-15	67.256 mi
Registration #8	2019-03-29	67.257 mi
Registration #9	2019-03-29	67.257 mi
Registration #10	2019-03-29	67.257 mi
Registration #11	2019-03-29	67.257 mi
Registration #12	2019-03-29	67.257 mi
Registration #13	2019-03-29	67.257 mi
Registration #14	2019-03-29	67.257 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1170 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	D13A-1595025