



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2009
Top speed	125 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I








Internet history

Entry 1

Date	2021-06-20
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-11-28
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #12 2021-11-26 13:37

MOT test number 185297669858

Result ✓ Passed

Next expiry date 2022-11-28

- Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-11-27 16:57

MOT test number 681846551802

Result ✓ Passed

**MOT #10**

2019-05-24 09:35

**MOT test number**

608921365231

**Result**

✓ Passed

- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #9**

2018-05-23 12:26

**MOT test number**

737764445733

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8**

2017-05-16 11:19

**MOT test number**

329760349672

**Result**

✓ Passed

**MOT #7**

2017-04-08 09:52

**MOT test number**

839250123443

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Headlamp aim too low (1.8)
- Advice** Offside Rear Tyre worn close to the legal limit Nail In tyre (4.1.E.1)

**MOT #6** 2016-05-27 15:50**MOT test number** 302607492896**Result** ✓ Passed**MOT #5** 2015-05-29 18:42**MOT test number** 288369845159**Result** ✓ Passed**Notice** No emission test results registered**MOT #4** 2014-04-15 18:52**MOT test number** 627535304135**Result** ✓ Passed**MOT #3** 2014-04-15 10:54**MOT test number** 467975504108**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Rear Stop lamp remains on when the brakes are released (1.2.1e)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2013-03-13 12:35**MOT test number** 337232873060**Result** ✓ Passed**MOT #1** 2012-03-21 12:21**MOT test number** 118181282479**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
25 May 2022

X

MOT

Expired:  
28 November 2022

Tax status	Expired at 25 May 2022
Days left	706 days too late
MOT expiry date	28 November 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>WK09WXR</b>
Plate since	2024-03-29
Current registration	<b>WK09WXR</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-03-06
Last registration	2021-11-26
Complete history	<a href="#">See info</a>



Registration #1	2009-03-06	27 mi
Registration #2	2012-03-21	15.186 mi
Registration #3	2013-03-13	20.593 mi
Registration #4	2014-04-15	24.503 mi
Registration #5	2014-04-15	24.503 mi
Registration #6	2015-05-29	24.531 mi
Registration #7	2016-05-27	27.797 mi
Registration #8	2016-05-27	27.797 mi
Registration #9	2016-05-27	27.797 mi
Registration #10	2016-05-27	27.797 mi
Registration #11	2016-05-27	27.797 mi
Registration #12	2016-05-27	27.797 mi
Registration #13	2016-05-27	27.797 mi
Registration #14	2016-05-27	27.797 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG