




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V HIGHLINE BMT
Colour	White
Year of manufacture	2018
Top speed	94 mph
0 - 100 km/h	11.6 seconds
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-18
Pictures	9
Listing price	<a href="#">View report</a>



source: [heycar.co.uk](#)

Entry 1

Date	2021-07-16
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2025-03-28
<b>MOT pass rate</b>	100 %
<b>MOT passed</b>	4
<b>Failed MOT tests</b>	0
<b>Total advice items</b>	12
<b>Total items failed</b>	0

<b>MOT #4</b>	2024-03-04 12:21
<b>MOT test number</b>	683786572987
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-03-28
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #3</b>	2023-03-17 11:22
<b>MOT test number</b>	874510036778
<b>Result</b>	✓ Passed
<b>Advice</b>	Emissions too low to record

<b>MOT #2</b>	2022-03-14 10:35
<b>MOT test number</b>	188298676360
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Emissions too low to record
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1		2021-03-29 06:56
MOT test number		967271212719
Result		✓ Passed
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
28 March 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	28 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 320,00,-
<b>Standard rate (6 months)</b>	£ 176,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>WK18ODF</b>
Plate since	2019-06-29
Current registration	<b>WK18ODF</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-29
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2018-03-29	12 mi
Registration #2	2021-03-29	28.633 mi
Registration #3	2022-03-29	29.277 mi
Registration #4	2023-03-29	29.277 mi
Registration #5	2023-03-29	29.277 mi
Registration #6	2023-03-29	29.277 mi
Registration #7	2024-03-04	29.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2397 mm
Height	1990 mm
Length	5304 mm
Wheel base	3400 mm
Kerb weight	1942 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	3
Number of axles	2
Engine number	CXGB122204