



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





MOT history

MOT expiry date	2024-10-24
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	24
Total items failed	22

MOT #20 2023-10-25 18:37

MOT test number 224295581693

Result ✓ Passed

Next expiry date 2024-10-24

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Brake pipe corroded, covered in grease or other material Both front to rears (1.1.11 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #19 2023-10-17 17:33

MOT test number 842333923708

Result ✗ Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Brake pipe corroded, covered in grease or other material Both front to rears (1.1.11 (c))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #18** 2022-09-29 15:47**MOT test number** 926041331553**Result** ✓ Passed**MOT #17** 2022-09-28 09:50**MOT test number** 183528109854**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Headlamp aim too high and too far to the left. (4.1.2 (a))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #16 2021-07-28 13:58**MOT test number** 206510102124**Result** ✓ Passed**MOT #15** 2021-07-17 11:02**MOT test number** 987531757512**Result** ✗ Failed

- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill at rear corroded / holed within area of axle mtg. Been filled with cataloy (5.3.6 (a) (i))
- Advice** Offside DRL inop
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #14** 2020-08-10 15:50**MOT test number** 940760629919**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #13** 2019-08-14 14:18**MOT test number** 629022599424**Result** ✓ Passed**MOT #12** 2019-08-14 09:25**MOT test number** 959167918722**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2018-07-30 13:19**MOT test number** 600498345049**Result** ✓ Passed**Advice** Exhaust heat shields loose**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-07-27 14:25**MOT test number** 591790058734**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust heat shields loose**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #9** 2017-07-21 08:48**MOT test number** 144077609378**Result** ✓ Passed**MOT #8** 2017-07-21 08:48**MOT test number** 380285922647**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2016-07-25 15:43**MOT test number** 751426167810**Result** ✓ Passed**MOT #6** 2015-07-23 10:34**MOT test number** 859834305238**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-07-18 17:31**MOT test number** 725019594105**Result** ✓ Passed**MOT #4** 2014-07-18 11:51**MOT test number** 269259394179**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside rear brake binding (3.7.B.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Fail** Nearside rear brake binding (3.7.B.1)**MOT #3** 2013-07-17 14:02**MOT test number** 539518393107**Result** ✓ Passed**MOT #2** 2013-07-17 12:15**MOT test number** 745248193191**Result** ✗ Failed**Fail** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #1** 2012-07-20 10:53**MOT test number** 777752202229**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SM09TXX
Plate since	2019-09-28
Current registration	SM09TXX
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-07-27
Last registration	2023-10-25
Complete history	See info



Registration #1	2009-07-27	7 mi
Registration #2	2012-07-20	25.341 mi
Registration #3	2013-07-17	38.017 mi
Registration #4	2013-07-17	38.017 mi
Registration #5	2014-07-18	51.694 mi
Registration #6	2014-07-18	51.694 mi
Registration #7	2015-07-23	58.315 mi
Registration #8	2016-07-25	63.376 mi
Registration #9	2017-07-21	67.645 mi
Registration #10	2017-07-21	67.645 mi
Registration #11	2018-07-27	75.301 mi
Registration #12	2019-07-27	81.377 mi
Registration #13	2019-07-27	81.377 mi
Registration #14	2019-07-27	81.377 mi
Registration #15	2019-07-27	81.377 mi
Registration #16	2019-07-27	81.377 mi
Registration #17	2019-07-27	81.377 mi
Registration #18	2019-07-27	81.377 mi
Registration #19	2019-07-27	81.377 mi
Registration #20	2019-07-27	81.377 mi
Registration #21	2019-07-27	81.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D043269
---------------	---------