





report date: 2024-03-28

General information

Make	MERCEDES
Model	E E240 ELEGANCE
Colour	Blue
Year of manufacture	1999
Top speed	133 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	225 Nm at 3.000 rpm
Engine capacity	2.398 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.2 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-17

Pictures 43

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-15
Pictures	6
Listing price	View report









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2021-10-07
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	14
Total items failed	11

MOT #18	2020-10-06 11:43
MOT test number	397112755741
Result	✓ Passed
Next expiry date	2021-10-07

MOT #17		2020-10-06 11:43
MOT test number		574272655032
Result		× Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #16	2019-10-08 15:34
MOT test number	400030163711
Result	✓ Passed
Minor Offside Obligatory mirror slightly loose (3.3 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #15 2019-10-07 12:07

MOT test number 976183521534

Result X Failed

MAJOR Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Nearside Rear Brake hose excessively chafed (1.1.12 (b) (ii))

MAJOR Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Brake hose excessively chafed (1.1.12 (b) (ii))

MOT #14 2018-01-03 11:05

MOT test number 145849996522

Advice Front Outer Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement both sides (2.4.G.2)

Advice Oil leak

MOT #13 2018-01-02 13:35

MOT test number 477743818629

Result X Failed

Advice Oil leak

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Front Outer Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement both sides (2.4.G.2)

MOT #12 2016-05-12 08:45

MOT test number 885384252070

CarCheck.co.uk page 4/13



report date: 2024-03-28

 MOT #11
 2015-01-15 11:27

 MOT test number
 477895715027

 Result
 ✓ Passed

 MOT #10
 2015-01-15 11:27

 MOT test number
 928235115000

 Result
 X Failed

 Pass with rectification
 Offside Stop lamp not working (1.2.1b)

MOT #9

MOT test number

2013-07-10 11:00

256401393458

Result

✓ Passed

MOT #8 2013-07-09 11:40 457970693145 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Stop lamp not working (1.2.1b) Offside Headlamp aim too low (1.8) Fail Fail Offside Rear Direction indicator flashing more than 120 times a minute (1.4.A.2g) Fail Windscreen washer provides insufficient washer liquid (8.2.3) Fail Nearside Headlamp aim too low (1.8) Fail Offside Front Direction indicator not working (1.4.A.2c) Fail Horn not working (1.6.2a)

 MOT #7
 2012-07-05 11:52

 MOT test number
 368137782199

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6	2011-06-04 13:41
MOT test number	458275351105
Result	✓ Passed
MOT #5	2010-06-04 15:52
MOT test number	381435850135
Result	✓ Passed
Advice Lower Suspension arm has slight play in a ball joint (2.4.G.2)	

MOT #4		2009-06-08 17:48
MOT test	number	750379159129
Result		✓ Passed
Advice	Nearside Front Front suspension has slight play in a lower suspension	ball joint (2.5.B.1a)

MOT #3	2008-05-30 15:30
MOT test number	292381158494
Result	✓ Passed
MOT #2	2007-05-22 16:15
MOT test number	234592547490
Result	✓ Passed
MOT #1	2006-05-17 11:30
MOT test number	951177036122
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check





Tax status	Expired at 16 September
Days left	955 days too late
MOT expiry date	7 October 2021

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	





Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

Owner history

o mile. History	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloadere.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	1999-07-30
Last registration	2020-10-06
Complete history	See info



Registration #1	1999-07-30	14 mi
Registration #2	2006-05-17	36.670 mi
Registration #3	2007-05-22	41.634 mi
Registration #4	2008-05-30	46.893 mi
Registration #5	2009-06-08	51.703 mi
Registration #6	2010-06-04	56.793 mi
Registration #7	2011-06-04	60.710 mi
Registration #8	2012-07-05	63.720 mi
Registration #9	2013-07-09	67.751 mi
Registration #10	2013-07-10	67.757 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		91,709 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 12/13



T622DETreport date: 2024-03-28

		_		
- I) I m	ancian	C).	\mathbf{w}	nt.
וווט	ension	3 UX	weiu	III.

Width	1995 mm
Height	1436 mm
Length	4795 mm
Kerb weight	1505 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11291130374441

CarCheck.co.uk page 13/13