





report date: 2024-03-28

## General information

Make	FORD
Model	KA TITANIUM
Colour	Red
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



SB15AKK report date: 2024-03-28

Internet history

F	n	r۱	,	1

Life y 1	
Date	2021-09-04
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-16
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	4
Total items failed	7

MOT #9	2023-06-17 11:21
MOT test number	677132681436
Result	<b>✓</b> Passed
Next expiry date	2024-06-16

MOT #8		2023-06-17 11:21
MOT test number		576853846473
Result		<b>X</b> Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	

MOT #7	2022-08-18 09:41
MOT test number	915227885340
Result	✓ Passed
MOT #6	2021-09-20 10:45
MOT test number	845573685638
Result	✓ Passed
MOT #5	2020-12-31 13:45
MOT test number	890787371068
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT #4** 2020-12-28 15:38 425828884984 **MOT** test number Result × Failed Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c)) **Advice** Rear Exhaust mounting defective clamp missing (6.1.2 (a))

MOT #3

MOT test number

948540031444

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

 MOT #1
 2018-06-29 08:05

 MOT test number
 577920352347

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manus .	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



SB15AKK report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-09
Last registration	2023-06-17
Complete history	See info



Registration #1	2015-05-09	10 mi
Registration #2	2018-06-29	15.696 mi
Registration #3	2019-06-20	21.936 mi
Registration #4	2019-06-21	21.936 mi
Registration #5	2020-12-28	31.721 mi
Registration #6	2020-12-31	31.725 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

# Additional information

Fuel tank capacity	35 l
Number of axles	2
Engine number	1361424

CarCheck.co.uk page 11/11