





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | GOLF MATCH TSI |
| Colour | Grey |
| Year of manufacture | 2008 |
| Top speed | 122 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 122 BHP |
|-------------------------|---------------------|
| Max. torque | 201 Nm at 1.500 rpm |
| Engine capacity | 1.390 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.5 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

Date 2021-08-09

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

| Date | 2021-06-26 |
|------|------------|
|------|------------|

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-05-23 |
|------|------------|

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-03-13 |
|--------------------|------------|
| MOT pass rate | 93 % |
| MOT passed | 14 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 3 |

| MOT #15 | 2024-03-14 17:04 |
|--|------------------|
| MOT test number | 573964282231 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-13 |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #14 | 2023-03-10 12:16 |
|-----------------|------------------|
| MOT test number | 921084097514 |
| Result | ✓ Passed |
| | |
| MOT #13 | 2022-06-15 12:19 |
| MOT test number | 289355247555 |
| Result | ✓ Passed |
| | |
| MOT #12 | 2021-10-01 09:01 |
| MOT test number | 536154958022 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



Result

YR58FPZ

report date: 2024-03-29

✓ Passed

MOT #11 2020-10-01 08:18 **MOT** test number 860374261243 ✓ Passed Result **Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Nearside Front Inner Tyre worn close to legal limit/worn on edge On limit (5.2.3 (e)) **Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice Advice Offside Front Inner Tyre worn close to legal limit/worn on edge On limit (5.2.3 (e)) Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) **Advice**

| MOT #10 | 2019-09-03 12:15 |
|--|------------------|
| MOT test number | 262824032830 |
| Result | ✓ Passed |
| Minor Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | |

| MOT #9 | 2018-09-20 13:14 |
|-----------------|------------------|
| MOT test number | 511539606208 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2017-09-20 08:32 |
| MOT test number | 963922524444 |

| MOT # | 7 | 2017-09-19 09:17 |
|--|---|------------------|
| MOT te | est number | 136889252420 |
| Result | | × Failed |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b) | | |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |

CarCheck.co.uk page 4/12



report date: 2024-03-29

| MOT #6 | 2016-09-22 13:14 |
|-----------------|------------------|
| MOT test number | 765539598012 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2015-08-27 00:00 |
| MOT test number | 189034143070 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2014-08-27 11:11 |
| MOT test number | 228039034245 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2013-08-19 12:30 |
| MOT test number | 499591333233 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2012-08-21 13:14 |
| MOT test number | 349244632225 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2011-08-23 11:17 |
| MOT test number | 196945831226 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 13 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

Damage 2

| Date | |
|----------|--|
| Category | |





Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| Owner history | |
|---|--|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere. | |
| | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| Plate changes | More info > |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | SK UK |
| Plate since | |
| Current registration | NK SIN |
| Plate since | |
| | More info > |
| | |
| | |

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 19 |
| First mileage registration | 2008-09-18 |
| Last registration | 2024-03-14 |
| Complete history | See info |



| Registration #1 | 2008-09-18 | 6 mi |
|-----------------------------------|------------|------------------------|
| Registration #2 | 2011-08-23 | 18.414 mi |
| Registration #3 | 2012-08-21 | 23.159 mi |
| Registration #4 | 2013-08-19 | 27.953 mi |
| Registration #5 | 2014-08-27 | 34.522 mi |
| Registration #6 | 2015-08-27 | 42.981 mi |
| Registration #7 | 2016-09-22 | 52.761 mi |
| Registration #8 | 2017-09-19 | 97.369 mi |
| Registration #9 | 2017-09-20 | 67.376 mi |
| Registration #10 | 2018-09-20 | 79.871 mi |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.117 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | |
| | | |
| Registration #16 | | 11.777 es |
| Registration #16 Registration #17 | | 11.777 es |
| - | | 11.777 es 11.777 es |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1759 mm |
|---------------------|---------|
| Height | 1479 mm |
| Length | 4204 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1205 kg |
| Max. allowed weight | 1820 kg |

Additional information

| Fuel tank capacity | 55 l |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| CarChack co.uk | nago 12/12 |

CarCheck.co.uk page 12/12

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CAX 036445 |