





report date: 2024-03-28

General information

| Make | VOLVO |
|---------------------|----------------|
| Model | C30 D DRIVE S |
| Colour | Blue |
| Year of manufacture | 2009 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 108 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 104 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2021-11-27


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-10-09

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-09-23

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| | 0004.00.00 |
|--------------------|------------|
| MOT expiry date | 2024-09-20 |
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

| MOT #13 | | 2023-09-20 13:16 |
|---|---|----------------------|
| MOT test | number | 307349926368 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-09-20 |
| Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge edge very low (5.2.3 (e)) | | |
| Advice Both rear tyres slight out of shape on inner edges n/s and o/s | | |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge edge very | very bad (5.2.3 (e)) |

| MOT #12 | 2022-09-16 13:33 |
|-----------------|------------------|
| MOT test number | 764417049512 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2021-09-21 16:55 |
| MOT test number | 714317017687 |

| 1101 #11 | 2021 03 21 10.33 |
|--|------------------|
| MOT test number | 714317017687 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2020-11-27 08:25 |
| MOT test number | 528590646623 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/12



MOT #9 2020-11-27 08:25

MOT test number 384281604105

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8 2019-11-14 09:21

MOT test number 650401984124

Result ✓ Passed

MOT #7 2018-10-18 08:48

MOT test number 228395173048

Result \rightarrow Passed

MOT #6 2017-11-13 15:12

MOT test number 319067296805

Result \(\sqrt{Passed} \)

Advice Offside and nearside front tyres badly worn on inner edges

MOT #5 2016-09-28 07:46

MOT test number 293563411792

Result
✓ Passed

Advice Os and nsr tyres starting to perish

MOT #4 2015-10-23 14:48

MOT test number 542547651908

CarCheck.co.uk page 4/12



| MOT #3 | 2014-10-13 16:40 |
|-----------------|------------------|
| MOT test number | 779926184274 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2013-10-24 16:59 |
| MOT test number | 488357693241 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2012-10-01 10:54 |
| MOT test number | 375065772484 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12





Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 216 |
| MOT expiry date | 20 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|--|-------------|
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | |
| Current registration | NK NK |
| Plate since | |
| Current registration | NK SIK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2009-10-09 |
| Last registration | 2023-09-20 |
| Complete history | See info |



| Registration #1 | 2009-10-09 | 17 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-10-01 | 21.823 mi |
| Registration #3 | 2013-10-24 | 27.306 mi |
| Registration #4 | 2014-10-13 | 28.392 mi |
| Registration #5 | 2015-10-23 | 29.219 mi |
| Registration #6 | 2016-09-28 | 33.494 mi |
| Registration #7 | 2017-11-13 | 41.071 mi |
| Registration #8 | 2018-10-18 | 47.933 mi |
| Registration #9 | 2019-11-14 | 53.424 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 91.777 es |
| Registration #16 | | 0.00 44 |
| Registration #17 | | 9.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1408 kg |
| Max. allowed weight | 1880 kg |

Additional information

| Fuel tank capacity | 52 l | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| Number of seats CarCheck.co.uk | 5 | age 12/12 |