




report date: 2024-09-18

General information

Make	MINI
Model	CLUBVAN COOPER D
Colour	Black
Year of manufacture	2013
Top speed	122 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-10-12
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-01
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #9 2024-04-02 15:45

MOT test number 974474767591

Result ✔ Passed

Next expiry date 2025-04-01

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2024-04-02 09:43

MOT test number 785376068501

Result ✘ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen not providing sufficient fluid (3.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #7	2023-02-02 16:13
MOT test number	399350715826
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2021-11-15 14:40
MOT test number	672209529471
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2020-11-30 09:24
MOT test number	989831444068
Result	✓ Passed

MOT #4	2019-12-06 10:31
MOT test number	564319239925
Result	✓ Passed

MOT #3	2018-12-05 10:55
MOT test number	614421648291
Result	✓ Passed

MOT #2	2017-12-08 11:51
MOT test number	851581725637
Result	✓ Passed



MOT #1 2016-11-26 10:23

MOT test number 877300948620

Result ✓ Passed

Advice Offside Front Small stone chip in screen



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
1 April 2025

Tax status	Valid until 1 April
Days left	171
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	




Damage 2

Date	
Category	
Type	



Extra MINI salvage check

 If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	LO63AZA
Plate since	2019-09-18
Current registration	LO63AZA
Plate since	2019-09-18

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-12-11
Last registration	2024-04-02
Complete history	See info



Registration #1	2013-12-11	24 mi
Registration #2	2016-11-26	28.268 mi
Registration #3	2017-12-08	41.403 mi
Registration #4	2018-12-05	53.039 mi
Registration #5	2019-12-06	61.979 mi
Registration #6	2020-11-30	71.159 mi
Registration #7	2021-05-01	71.277 mi
Registration #8	2021-05-01	71.277 mi
Registration #9	2021-05-01	71.277 mi
Registration #10	2021-05-01	71.277 mi
Registration #11	2024-04-02	71.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1426 mm
Length	3961 mm
Kerb weight	1185 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	76708710