



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | CITROEN |
| Model | NEMO HDI 8V |
| Colour | Red |
| Year of manufacture | 2010 |
| Top speed | 94 mph |
| 0 - 60 mph | 18.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 68 BHP |
| Max. torque | 160 Nm at 1.750 rpm |
| Engine capacity | 1.399 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-06-16 |
| Pictures | 9 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-09 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 14 |

MOT #15 2023-05-06 10:19

MOT test number 551079012880

Result ✓ Passed

Next expiry date 2024-05-09

Advice Nearside Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Axle corroded

MOT #14 2023-04-29 09:51

MOT test number 106498566122

Result ✗ Failed**Advice** Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Axle corroded**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2022-05-10 12:50**MOT test number** 795813392829**Result** ✓ Passed**MOT #12** 2022-05-10 11:45**MOT test number** 911535527354**Result** ✗ Failed**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2021-06-10 14:44**MOT test number** 556601736706**Result** ✓ Passed**MOT #10** 2021-06-09 14:09**MOT test number** 575144780674**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9**

2020-06-17 11:51

MOT test number

341853426646

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front top mount noisy / rough
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))
- Advice** Nearside Front top mount noisy / rough
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing low tread (5.2.3 (d) (ii))

MOT #8

2020-06-12 10:04

MOT test number

861987422795

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing low tread (5.2.3 (d) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front top mount noisy / rough
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))
- Advice** Nearside Front top mount noisy / rough
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp flickering when hazards operational (4.2.3 (c))
- Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

MOT #7

2019-03-22 13:03

MOT test number

263747421552

Result

✓ Passed



| | |
|---------------|------------------|
| MOT #6 | 2018-04-16 06:51 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 800664868637 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2017-04-10 06:51 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 861310290428 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2016-04-11 07:03 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 485300986924 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2015-04-07 11:14 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 539497395011 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2014-04-11 09:57 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 839451004196 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|-----------------------------|
| Notice | Osf tyre worn on inner edge |
|---------------|-----------------------------|

| | |
|---------------|--------------------------------|
| Notice | Nsf tyre wearing on inner edge |
|---------------|--------------------------------|

| | |
|---------------|------------------|
| MOT #1 | 2013-04-13 10:39 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 859163203144 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
9 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 9 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-04-20 |
| Last registration | 2023-05-06 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-04-20 | 18 mi |
| Registration #2 | 2013-04-13 | 19.295 mi |
| Registration #3 | 2014-04-11 | 24.450 mi |
| Registration #4 | 2015-04-07 | 30.652 mi |
| Registration #5 | 2016-04-11 | 37.273 mi |
| Registration #6 | 2017-04-10 | 42.726 mi |
| Registration #7 | 2018-04-16 | 48.669 mi |
| Registration #8 | 2019-03-22 | 57.634 mi |
| Registration #9 | 2020-06-12 | 72.318 mi |
| Registration #10 | 2021-06-20 | 85.377 mi |
| Registration #11 | 2022-06-20 | 95.377 mi |
| Registration #12 | 2023-06-20 | 105.377 mi |
| Registration #13 | 2024-06-20 | 115.377 mi |
| Registration #14 | 2025-06-20 | 125.377 mi |
| Registration #15 | 2026-06-20 | 135.377 mi |
| Registration #16 | 2027-06-20 | 145.377 mi |
| Registration #17 | 2028-06-20 | 155.377 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 59% |
| Children | 74% |
| Pedestrian | 55% |
| Safety systems | 29% |
| Overall rating | 58% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1816 mm |
| Height | 1721 mm |
| Length | 3959 mm |
| Wheel base | 2513 mm |
| Kerb weight | 1185 kg |
| Max. allowed weight | 1710 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FD982641028 |