



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 S D V50
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-08-26
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-07
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	45
Total items failed	3

MOT #17 2023-08-03 09:17

MOT test number 910783697769

Result ✓ Passed

Next expiry date 2024-08-07

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #16 2022-08-08 12:15

MOT test number 526452497891

Result ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Emissions high

**MOT #15**

2021-07-19 14:39

MOT test number

256539493712

Result

✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #14**

2021-07-19 08:00

MOT test number

946921583696

Result

✗ Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2020-07-20 14:05

MOT test number

701808396497

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #12**

2020-07-09 14:28

MOT test number

171307756988

Result

✗ Failed

Advice Rear exhaust box outer skin corroded**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #11** 2019-08-05 06:53**MOT test number** 646569704342**Result** ✓ Passed**Advice** Nearside Rear exhaust box corroded**MOT #10** 2018-09-20 08:18**MOT test number** 942454508810**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2018-09-15 08:24**MOT test number** 998762908879**Result** ✗ Failed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Rear Upper Position lamp not working (4.2.1 (a))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2017-09-16 08:06

MOT test number

841740980030

Result

✓ Passed

- Advice** Nearside Front Tyre inner edge worn smooth
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)
- Advice** Offside Front Tyre inner edge worn smooth

MOT #7

2016-09-16 13:32

MOT test number

324103184851

Result

✓ Passed

- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
rear (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
rear (2.4.G.2)

MOT #6

2015-09-21 14:18

MOT test number

607079498022

Result

✓ Passed

MOT #5

2015-09-19 08:04

MOT test number

952917357754

Result

✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #4** 2014-09-13 11:19**MOT test number** 789696054268**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2013-08-30 15:26**MOT test number** 887412643227**Result** ✓ Passed

Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #2 2013-08-30 15:26**MOT test number** 765602143228**Result** ✗ Failed

Pass with rectification Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

Advice Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Pass with rectification Offside Rear Direction indicators incorrect colour (1.4.A.2f)

MOT #1 2012-09-04 08:34**MOT test number** 218398842276**Result** ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Offside Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-21
Last registration	2023-08-03
Complete history	See info



Registration #1	2009-09-21	20 mi
Registration #2	2012-09-04	31.433 mi
Registration #3	2013-08-30	40.353 mi
Registration #4	2014-09-13	51.535 mi
Registration #5	2015-09-19	64.173 mi
Registration #6	2015-09-21	64.173 mi
Registration #7	2016-09-16	75.675 mi
Registration #8	2017-09-16	81.280 mi
Registration #9	2018-09-15	85.144 mi
Registration #10	2019-09-15	91.277 mi
Registration #11	2020-09-15	91.277 mi
Registration #12	2021-09-15	91.277 mi
Registration #13	2022-09-15	91.277 mi
Registration #14	2023-09-15	91.277 mi
Registration #15	2024-09-15	91.277 mi
Registration #16	2025-09-15	91.277 mi
Registration #17	2026-09-15	91.277 mi
Registration #18	2027-09-15	91.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1519 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	565929
---------------	--------