



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I LIMITED EDITION
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	14
Total items failed	8

MOT #16 2024-01-29 14:35

MOT test number 612893080166

Result ✓ Passed

Next expiry date 2025-02-22

Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15 2024-01-27 15:28

MOT test number 776236073919

Result ✗ Failed

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14** 2023-02-13 11:51**MOT test number** 463867355979**Result** ✓ Passed**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**MOT #13** 2023-02-13 11:51**MOT test number** 580583403048**Result** ✗ Failed**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps both (4.7.2 (a))**MOT #12** 2022-02-10 10:52**MOT test number** 106141480504**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-02-23 10:17**MOT test number** 663244714650**Result** ✓ Passed**MOT #10** 2020-08-24 12:17**MOT test number** 633642584311**Result** ✓ Passed**Advice** Nearside Front Lower Bumper mountings corroded but not likely to become detached front bumper NSF lower crack, but not likely to come off or show sharp edges (6.1.4 (a) (i))**Advice** Nearside Front Wheel/tyre protruding beyond wheel arch wheel arch worn out hit by tyre. not likely to come off.

**MOT #9** 2019-07-31 13:48**MOT test number** 238597616335**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2018-08-06 16:00**MOT test number** 277622006756**Result** ✓ Passed**MOT #7** 2017-10-18 13:59**MOT test number** 446523887250**Result** ✓ Passed**MOT #6** 2016-11-02 14:17**MOT test number** 783519307050**Result** ✓ Passed**MOT #5** 2015-10-20 11:42**MOT test number** 478847705631**Result** ✓ Passed**MOT #4** 2014-10-15 12:32**MOT test number** 277298984206**Result** ✓ Passed**MOT #3** 2013-10-16 14:17**MOT test number** 328989883499**Result** ✓ Passed**Notice** Nearside front tyre getting low and worn uneven on outer edge



MOT #2	2012-10-27 11:32
MOT test number	217791302376
Result	✓ Passed

MOT #1	2012-10-27 11:32
MOT test number	717121402391
Result	✗ Failed
Pass with rectification	Parking brake lever has no reserve travel (3.1.6b)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
22 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-30
Last registration	2024-01-29
Complete history	See info



Registration #1	2009-10-30	17 mi
Registration #2	2012-10-27	17.503 mi
Registration #3	2013-10-16	23.009 mi
Registration #4	2014-10-15	29.119 mi
Registration #5	2015-10-20	34.439 mi
Registration #6	2016-11-02	39.792 mi
Registration #7	2017-10-18	43.546 mi
Registration #8	2018-08-06	45.746 mi
Registration #9	2019-07-31	63.511 mi
Registration #10	2020-05-20	75.277 mi
Registration #11	2021-05-20	85.277 mi
Registration #12	2022-05-20	95.277 mi
Registration #13	2023-05-20	105.277 mi
Registration #14	2024-01-29	115.277 mi
Registration #15	2024-01-29	125.277 mi
Registration #16	2024-01-29	135.277 mi
Registration #17	2024-01-29	145.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4370 mm
Wheel base	2660 mm
Kerb weight	1425 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	3ZZV053758