



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 SPORT DCI S/R P/V
Colour	Silver
Year of manufacture	2014
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-05-04
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-07
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	24
Total items failed	2

MOT #9	2023-05-08 14:34
--------	------------------

MOT test number	804157479784
-----------------	--------------

Result	✓ Passed
Next expiry date	2024-05-07
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Nail in tyre both sides
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords 215/65/16c (5.2.3 (d) (i))
Advice	Nearside Front fog light out
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm & badly worn 215/65/16c (5.2.3 (e))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated top drop link cover (5.3.4 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords 215/65/16c (5.2.3 (d) (i))

**MOT #8**

2023-05-08 14:09

**MOT test number**

805500930992

**Result****✗ Failed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front fog light out
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm & badly worn 215/65/16c (5.2.3 (e))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords also 2mm & badly worn 215/65/16c (5.2.3 (d) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated top drop link cover (5.3.4 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords 215/65/16c (5.2.3 (d) (i))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords 215/65/16c (5.2.3 (d) (i))
- Advice** Rear Nail in tyre both sides
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7**

2022-04-28 10:33

**MOT test number**

454172014707

**Result****✓ Passed****MOT #6**

2021-06-14 11:31

**MOT test number**

542545855247

**Result****✓ Passed**

- Minor** Windscreen wiper blade defective (3.4 (b) (i))

**MOT #5** 2021-06-14 11:31**MOT test number** 393150698017**Result** ✗ Failed**Minor** Windscreen wiper blade defective (3.4 (b) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #4** 2020-06-16 09:40**MOT test number** 819237757948**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2019-05-22 11:15**MOT test number** 181776832067**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively Both (1.1.14 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #2** 2018-06-18 09:35**MOT test number** 743912374769**Result** ✓ Passed**MOT #1** 2017-06-15 08:49**MOT test number** 286114137704**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
7 May 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	7 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>YB14GYN</b>
Plate since	2019-09-29
Current registration	<b>YB14GYN</b>
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-18
Last registration	2023-05-08
Complete history	<a href="#">See info</a>



Registration #1	2014-07-18	26 mi
Registration #2	2017-06-15	40.949 mi
Registration #3	2018-06-18	55.370 mi
Registration #4	2019-05-22	69.005 mi
Registration #5	2020-06-16	78.717 mi
Registration #6	2021-06-14	86.608 mi
Registration #7	2022-05-20	95.277 mi
Registration #8	2022-05-20	95.277 mi
Registration #9	2022-05-20	95.277 mi
Registration #10	2022-05-20	95.277 mi
Registration #11	2023-05-08	95.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1904 mm
Height	1944 mm
Length	4784 mm
Kerb weight	1710 kg
Max. allowed weight	2790 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Number of axles	2

**Engine number**

C161336