





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC EX
Colour	Silver
Year of manufacture	2010
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-04

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-02-26
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #13	2024-02-20 16:34
MOT test number	417330870193
Result	× Failed
Advice Both front and offside rear tyres split and perished	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	

MOT #12	2023-02-22 15:47
MOT test number	991099970351
Result	✓ Passed
Advice Front tyres cracks in side walls	

MOT #11	2022-02-21 15:54
MOT test number	171294670865
Result	✓ Passed
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1
Advice Offside front tyre worn close to limit	
Advice Rear brake pads worn thin	
Advice Both rear tyre tread worn low and perished	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Rear Outer Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Advice

Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2021-01-28 13:31 **MOT** test number 884569294005 Result × Failed Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Advice Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail **Advice** Rear Outer Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii)) Fail Rear fog lamp not working (4.5.1 (a) (ii))

MOT #8	2020-01-30 09:37
MOT test number	283656515975
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #7	2019-02-14 16:20
MOT test number	436010856560
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2018-02-13 16:09
MOT test number	158739183458
Result	✓ Passed
MOT #5	2017-02-07 14:15
MOT test number	540538959712
Result	✓ Passed
MOT #4	2016-02-09 14:58
MOT test number	713151950343
Result	✓ Passed
MOT #3	2015-02-16 15:22
MOT test number	238197745066
Result	✓ Passed
MOT #2	2014-02-17 14:47
MOT test number	239078644041
Result	✓ Passed
MOT #1	2013-02-06 16:21
MOT test number	616997133007
Result	✓ Passed

CarCheck.co.uk page 5/12



CU59MVG report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	26 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

*		
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		А
MARKET CONTRACTOR CONT		

	More info	>
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		
Current registration	UK NE	
Flate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



CU59MVG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-02-26
Last registration	2024-02-20
Complete history	See info



Registration #1	2010-02-26	14 mi
Registration #2	2013-02-06	22.468 mi
Registration #3	2014-02-17	35.492 mi
Registration #4	2015-02-16	47.879 mi
Registration #5	2016-02-09	59.182 mi
Registration #6	2017-02-07	71.344 mi
Registration #7	2018-02-13	77.071 mi
Registration #8	2019-02-14	88.490 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1540 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1009450

CarCheck.co.uk page 12/12