





report date: 2024-03-29

#### General information

Make	PEUGEOT
Model	PARTNER BLUE HDI S/S TEPEE ALLURE
Colour	Grey
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

#### Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29


#### Internet history

#### Entry 1

Date 2021-12-21

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT HISTORY	Μ	OT	history
-------------	---	----	---------

MOT expiry date	2025-01-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #8	2024-01-10 14:01
MOT test number	842654863248
Result	✓ Passed
Next expiry date	2025-01-12

MOT #7	2023-01-13 16:04
MOT test number	464579881958
Result	<b>✓</b> Passed

MOT #6	2022-01-10 14:55
MOT test number	166262217155
Result	<b>✓</b> Passed

MOT #5		2021-08-16 11:38
MOT test	number	177523357640
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-08-16 09:49

**MOT test number** 537179001993

Result X Failed

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2020-09-03 16:17

**MOT test number** 420026607973

**Result** ✓ Passed

MOT #2 2019-08-09 12:37

**MOT test number** 598353815191

Result \( \sqrt{Passed} \)

**MOT #1** 2019-08-09 12:37

**MOT test number** 484577434994

**Result** X Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	12 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

# SF16AWV

report date: 2024-03-29

# For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>.

More info >

#### Plate changes

See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-04
Last registration	2024-01-10
Complete history	See info



Registration #1	2016-03-04	25 mi
Registration #2	2019-08-09	26.879 mi
Registration #3	2019-08-09	26.879 mi
Registration #4	2020-09-03	28.015 mi
Registration #5	2021-08-16	28.208 mi
Registration #6		11.777 es
Registration #6 Registration #7		11,777 es
-		11.777 es
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 10/11



SF16AWV
report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



## Dimensions & weight

Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11

**Engine number** 

JBHB3076096