





#### General information

Make	NISSAN
Model	370 Z V6 GT
Colour	White
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	328 BHP
Max. torque	363 Nm at 5.200 rpm
Engine capacity	3.696 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	36.2 mpg
Consumption combined	26.9 mpg
CO2 emission	247 g/km
CO2 label	L







### Internet history

Entry 1


Date Pictures 2021-09-03

32

Listing price

View report

SOUTHGROVE



source: autotrader.co.uk

CarCheck.co.uk



### MOT history

MOT expiry date	2024-04-03
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	6
Total items failed	4

MOT #12	2023-04-03 15:08
MOT test number	628651606349
Result	✓ Passed
Next expiry date	2024-04-03

MOT #11	2022-04-04 14:01
MOT test number	116521493369
Result	✓ Passed

MOT #10	2021-01-08 09:01
MOT test number	868436180783
Result	Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #9	2020-01-08 15:08
MOT test number	547834491906
Result	✓ Passed





MOT #8	2020-01-07 11:53
MOT test number	459587447711
Result	🗙 Failed
<b>Fail</b> Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3	(g) (ii))
Fail Nearside Rear Valve stem seriously damaged (5.2.3 (j))	
Fail Windscreen washer not working (3.5 (a))	
Fail Offside Rear Valve stem seriously damaged (5.2.3 (j))	

MOT #7	2019-01-04 09:49
MOT test number	697572866260
Result	✓ Passed
Result	✓ Passe

МОТ #6	2018-01-04 10:10
MOT test number	684899878865
Result	✓ Passed

MOT #5	2017-01-07 10:42
MOT test number	640149484620
Result	✓ Passed
Advice Nearside Front tyre has damage to outer wall but not exposing cords	
Advice Offside Rear tyre has small cut in outer wall but not exposing cords	

MOT #4	2016-01-08 11:02
MOT test number	238960566131
Result	✓ Passed





MOT #3		2015-01-02 13:50
MOT test	number	509482505008
Result		✓ Passed
Notice Notice	Engine covers fitted obscuring some components in the engine bay Under-trays fitted obscuring some underside components	
MOT #2		2014-01-03 09:47
MOT test	number	856133604028
Result		Passed

MOT #1	2013-03-26 09:36
MOT test number	195655283086
Result	✓ Passed





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



OY10PDU report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-03-31
Last registration	2023-04-03
Complete history	See info



Registration #1	2010-03-31	13 mi
Registration #2	2013-03-26	14.676 mi
Registration #3	2014-01-03	21.988 mi
Registration #4	2015-01-02	31.944 mi
Registration #5	2016-01-08	36.435 mi
Registration #6	2017-01-07	38.199 mi
Registration #7	2018-01-04	42.408 mi
Registration #8		11.777 esi
Registration #8 Registration #9		11.577 es
-		0.000 est 0.000 est 0.000 est
Registration #9		0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





#### Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1845 mm
Height	1315 mm
Length	4250 mm
Wheel base	2550 mm
Kerb weight	1508 kg
Max. allowed weight	1800 kg

### Additional information

Fuel tank capacity	72
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	140426