



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Pink
Year of manufacture	2009
Top speed	93 mph
0 - 60 mph	13.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-05-23
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-05-11
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	8
Total items failed	6

MOT #17	2024-04-27 10:50
MOT test number	379587433328
Result	✓ Passed
Next expiry date	2025-05-11
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive o/s and n/s (5.3.6 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material o/s and n/s (1.1.11 (c))
Advice	Rear Coil spring corroded o/s and n/s (5.3.1 (b) (i))

MOT #16	2023-04-20 09:07
MOT test number	221531234722
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Brake pipe corroded, covered in grease or other material all brake pipes (1.1.11 (c))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #15	2022-04-21 15:02
MOT test number	791045124652
Result	✓ Passed

**MOT #14** 2021-05-12 09:29**MOT test number** 403264241480**Result** ✓ Passed**MOT #13** 2020-06-29 14:05**MOT test number** 224948562682**Result** ✓ Passed**MOT #12** 2020-06-26 10:03**MOT test number** 174639682046**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11** 2019-04-17 15:30**MOT test number** 698469511775**Result** ✓ Passed**MOT #10** 2019-04-17 13:47**MOT test number** 787047666148**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #9** 2018-04-13 08:05**MOT test number** 476430949987**Result** ✓ Passed**MOT #8** 2017-04-19 15:48**MOT test number** 196539966305**Result** ✓ Passed

**MOT #7** 2017-04-19 12:27**MOT test number** 777292264482**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Driver's airbag obviously defective (5.4.1)**MOT #6** 2016-04-04 08:06**MOT test number** 894662480377**Result** ✓ Passed**MOT #5** 2015-04-17 12:04**MOT test number** 845577405106**Result** ✓ Passed**MOT #4** 2015-04-09 14:52**MOT test number** 518969395083**Result** ✗ Failed**Fail** Rear Road wheel distorted (4.2.A.1a)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-04-11 13:51**MOT test number** 478871404175**Result** ✓ Passed**MOT #2** 2013-04-24 15:52**MOT test number** 677174713175**Result** ✓ Passed



MOT #1	2012-04-17 09:54
MOT test number	416728002154
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
11 May 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	11 May 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-05-22
Last registration	2024-04-27
Complete history	<a href="#">See info</a>



Registration #1	2009-05-22	16 mi
Registration #2	2012-04-17	5.926 mi
Registration #3	2013-04-24	7.183 mi
Registration #4	2014-04-11	11.896 mi
Registration #5	2015-04-09	17.654 mi
Registration #6	2015-04-17	17.828 mi
Registration #7	2016-04-04	21.990 mi
Registration #8	2017-04-19	25.094 mi
Registration #9	2017-04-19	25.094 mi
Registration #10	2018-04-13	27.323 mi
Registration #11	2019-04-09	31.377 mi
Registration #12	2019-04-09	31.377 mi
Registration #13	2019-04-09	31.377 mi
Registration #14	2019-04-09	31.377 mi
Registration #15	2019-04-09	31.377 mi
Registration #16	2019-04-09	31.377 mi
Registration #17	2019-04-09	31.377 mi
Registration #18	2019-04-09	31.377 mi
Registration #19	2019-04-09	31.377 mi

More info >



## Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	<a href="#">see crash video</a>



## Dimensions &amp; weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	880 kg
Max. allowed weight	1250 kg

## Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1012019