



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Gold
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-18
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-01
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #10	2024-03-02 18:04
MOT test number	322769851124
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2024-03-02 18:04
MOT test number	782199218829
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2023-01-13 17:42
MOT test number	495396953355
Result	✓ Passed



MOT #7	2021-10-08 11:21
MOT test number	518916750365
Result	✓ Passed
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))

MOT #6	2021-03-24 14:30
MOT test number	855220344874
Result	✓ Passed
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5	2021-01-02 14:53
MOT test number	632758853058
Result	✗ Failed
Fail	Front Brake pad(s) worn down to wear indicator nearside and offside (1.1.13 (a) (i))
Fail	Rear Brake disc significantly and obviously worn nearside and offside (1.1.14 (a) (i))
Fail	Rear Brake pad(s) worn down to wear indicator nearside and offside (1.1.13 (a) (i))
Fail	Front Brake disc significantly and obviously worn nearside and offside (1.1.14 (a) (i))

MOT #4	2020-01-03 11:45
MOT test number	719521677036
Result	✓ Passed

MOT #3	2020-01-03 11:45
MOT test number	713112822966
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #2	2019-01-02 13:14
MOT test number	232557644606
Result	✓ Passed
Advice	Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))

MOT #1	2018-01-03 16:25
MOT test number	885995155881
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN12VXB
Plate since	2019-03-29
Current registration	EN12VXB
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-07-01
Last registration	2024-03-02
Complete history	See info



Registration #1	2012-07-01	9 mi
Registration #2	2018-01-03	66.355 mi
Registration #3	2019-01-02	80.484 mi
Registration #4	2020-01-03	84.755 mi
Registration #5	2020-01-03	84.755 mi
Registration #6	2021-01-02	86.769 mi
Registration #7	2022-01-02	88.783 mi
Registration #8	2022-01-02	88.783 mi
Registration #9	2022-01-02	88.783 mi
Registration #10	2022-01-02	88.783 mi
Registration #11	2022-01-02	88.783 mi
Registration #12	2024-03-02	90.797 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC995094
---------------	-------------