





report date: 2024-03-28

General information

Make	FORD
Model	KUGA TITANIUM TDCI
Colour	Grey
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-28

MOT history

MOT #14 2020-11-17 11:03 **MOT** test number 968322545868 Result ✓ Passed **Next expiry date** 2021-11-16 Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice

MOT #13 2020-11-17 11:02 **MOT** test number 971192409866 Result × Failed Pass with rectification Offside Headlamp aim too high (4.1.2 (a)) Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice**

MOT #12	2019-05-09 12:07
MOT test number	334139959547
Result	✓ Passed
MOT #11	2018-05-02 16:39
MOT test number	116657299525
Result	✓ Passed

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT #10	2018-04-30 16:28
MOT test number	984685081409
Result	× Failed
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Fail Offside Front coil spring broken (2.4.C.1a)	

MOT #9	2017-03-17 12:19
MOT test number	169111577248
Result	✓ Passed
MOT #8	2016-08-26 09:04
MOT test number	959930450006
Result	✓ Passed
MOT #7	2015-08-13 08:47
MOT test number	833220026758
Result	✓ Passed
MOT #6	2015-08-11 13:01
MOT test number	509503325266
Result	X Failed
Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2014-08-22 16:25
MOT test number	139274834236
Result	✓ Passed

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #4

MOT test number

Result

Nearside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #3

MOT test number

489487223265

Result

MOT #2

2012-03-03 11:56

MOT test number

769673662091

Result

Notice Rear number plate slightly de-laminated

MOT #1

MOT test number

Result

Pass with rectification

Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice

Rear number plate slightly de-laminated

Pass with rectification

Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

\sim		
Owner	hictory	7
OWITCE	1113601	1

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK ZIS ZIS
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-03-07
Last registration	2020-11-17
Complete history	See info



Registration #1	2009-03-07	29 mi
Registration #2	2012-03-03	39.230 mi
Registration #3	2013-08-15	76.857 mi
Registration #4	2014-08-22	111.077 mi
Registration #5	2014-08-22	111.077 mi
Registration #6	2015-08-11	123.382 mi
Registration #7	2015-08-13	123.382 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 9/10



BN09LFK report date: 2024-03-28

Car features

The FORD factory car options list is only available in the premium report.	
S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1842 mm
Height	1677 mm
Length	4443 mm
Kerb weight	1613 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 10/10

Engine number

9R89811