





report date: 2024-03-28

### General information

Make	FIAT
Model	DOBLO 16V CRC ACTIVE MULTIJET
Colour	White
Year of manufacture	2015
Top speed	97 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 1

Date 2022-05-27

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



WV15PLO report date: 2024-03-28

MOT history

MOT expiry date	2025-01-29
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	21
Total items failed	0

MOT #9	2024-01-15 12:36
MOT test number	781702425914
Result	✓ Passed
Next expiry date	2025-01-29
Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2024-01-15 10:34
MOT test	number	366585719745
Result		<b>X</b> Failed
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> adjustmen	Parking brake efficiency only just met. It would appear that the braking system at or repair. (1.4.2 (a) (i))	n requires
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2023-01-28 12:47
MOT test number 964075573651

Result 

Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6 2022-01-25 10:17

MOT test number 385410332971

Result \( \sqrt{Passed} \)

**MOT #5** 2022-01-17 10:50

**MOT test number** 442345939791

Result X Failed

MAJOR Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Unable to see brakes clearly due to wheel trims fitted

MAJOR Offside Front Service brake excessively binding (1.2.1 (f))

Minor Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #4 2021-01-18 10:15

**MOT test number** 377783726974

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-01-27 13:11

**MOT test number** 519758045369

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2	2019-01-07 09:13
MOT test number	517752167502
Result	✓ Passed
MOT #1	2018-01-30 23:12
MOT test number	392046628668
Result	✓ Passed
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice Parking brake lever has little reserve travel (3.1.6b)	

CarCheck.co.uk page 5/12



WV15PLO report date: 2024-03-28

Tax & MOT check





Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

$\sim$		
Owner	hictory	7
OWITCE	1113601	1

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report	
**************************************	
**************	
HARMAN CO.	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



**NV15PLO** 

report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12





report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-30
Last registration	2024-01-15
Complete history	See info



Registration #1	2015-03-30	16 mi
Registration #2	2018-01-30	16.039 mi
Registration #3	2019-01-07	21.396 mi
Registration #4	2020-01-27	30.486 mi
Registration #5	2021-01-18	65.016 mi
Registration #6	2022-01-17	93.567 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10,100 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1465 kg
Max. allowed weight	2190 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

5624341