



HONDA



A060HWC

report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Red
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 3


Date	2023-01-18
Pictures	47
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2

Date	2022-02-15
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-02-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	7
Total items failed	0

MOT #12	2024-01-12 09:37
MOT test number	469626514830
Result	✓ Passed
Next expiry date	2025-02-01

MOT #11	2023-01-24 15:04
MOT test number	595454200578
Result	✓ Passed

MOT #10	2022-02-02 14:16
MOT test number	374140018547
Result	✓ Passed

MOT #9	2021-03-09 10:11
MOT test number	352361059912
Result	✓ Passed

MOT #8	2020-03-11 17:04
MOT test number	689546272928
Result	✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #7** 2019-03-15 07:50**MOT test number** 980052003247**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perishing, small stone cuts and stones embedding (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perishing, small stone cuts and stones embedding (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre slightly damaged/cracking or perishing Perishing, small stone cuts (5.2.3 (d) (ii))**MOT #6** 2018-08-16 11:57**MOT test number** 702359574505**Result** ✓ Passed**MOT #5** 2017-09-13 06:54**MOT test number** 498247536466**Result** ✓ Passed**MOT #4** 2016-10-12 08:49**MOT test number** 929395118647**Result** ✓ Passed**MOT #3** 2015-10-14 08:04**MOT test number** 853903454551**Result** ✓ Passed**MOT #2** 2014-11-12 11:04**MOT test number** 695256114359**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-10-29 10:22
MOT test number	917892003357
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
1 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-11-23
Last registration	2024-01-12
Complete history	See info



Registration #1	2010-11-23	15 mi
Registration #2	2013-10-29	3.274 mi
Registration #3	2014-11-12	4.681 mi
Registration #4	2015-10-14	6.178 mi
Registration #5	2016-10-12	7.526 mi
Registration #6	2017-09-13	8.878 mi
Registration #7	2018-08-16	13.017 mi
Registration #8	2019-03-15	15.306 mi
Registration #9	2019-03-15	15.306 mi
Registration #10	2019-03-15	15.306 mi
Registration #11	2019-03-15	15.306 mi
Registration #12	2019-03-15	15.306 mi
Registration #13	2019-03-15	15.306 mi
Registration #14	2019-03-15	15.306 mi
Registration #15	2019-03-15	15.306 mi
Registration #16	2019-03-15	15.306 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1016382