



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D5 SE SPORT
Colour	Blue
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-07-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	17
Total items failed	11

MOT #17 2023-09-21 07:45

MOT test number 601659919943

Result ✓ Passed

Next expiry date 2024-09-26

Advice Offside Rear Inner Tyre slightly damaged Out of shape (5.2.3 (d) (ii))

Advice Nearside Rear Inner Tyre slightly damaged Out of shape (5.2.3 (d) (ii))

MOT #16 2022-09-27 14:23

MOT test number 598069464030

Result ✓ Passed

MOT #15 2021-09-24 15:51

MOT test number 431052511134

Result ✓ Passed

MOT #14 2021-03-30 10:09

MOT test number 841163885446

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre edges slightly wearing

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2019-04-26 16:23**MOT test number** 843530642241**Result** ✓ Passed**Advice** Offside Front Headlamp slight condensation**MOT #12** 2018-04-06 08:13**MOT test number** 144721515844**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to the legal limit EDGE WORN (4.1.E.1)**MOT #11** 2018-04-05 10:14**MOT test number** 273978708001**Result** ✗ Failed**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Inner Tyre worn close to the legal limit EDGE WORN (4.1.E.1)**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm EDGE WORN TO EXCESS/CUT (4.1.E.1)**MOT #10** 2017-04-06 09:38**MOT test number** 154876652400**Result** ✓ Passed**Advice** Front tyres worn on inner edges**Advice** Nearside front tyre has cut in side wall

**MOT #9** 2017-04-03 10:32**MOT test number** 275189490151**Result** ✗ Failed**Fail** Nearside Front Headlamp cleaning device inoperative (1.7.2)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside front tyre has cut in side wall**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Headlamp cleaning device inoperative (1.7.2)**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front tyres worn on inner edges**MOT #8** 2016-04-13 16:40**MOT test number** 538787115166**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-04-13 16:40**MOT test number** 653726621648**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-04-20 12:18**MOT test number** 739610315111**Result** ✓ Passed**Notice** Nail in nearside rear tyre

**MOT #5** 2014-04-22 14:45**MOT test number** 458782114107**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2014-04-22 14:45**MOT test number** 218272214100**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Pass with rectification** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2013-04-22 12:59**MOT test number** 456622213177**Result** ✓ Passed**MOT #2** 2012-04-26 16:09**MOT test number** 449317112196**Result** ✓ Passed**MOT #1** 2011-04-27 09:41**MOT test number** 748947211180**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-07
Last registration	2023-09-21
Complete history	See info



Registration #1	2007-11-07	23 mi
Registration #2	2011-04-27	32.219 mi
Registration #3	2012-04-26	36.437 mi
Registration #4	2013-04-22	40.671 mi
Registration #5	2014-04-22	44.569 mi
Registration #6	2015-04-20	48.130 mi
Registration #7	2016-04-13	51.606 mi
Registration #8	2016-04-13	51.606 mi
Registration #9	2017-04-03	54.944 mi
Registration #10	2018-04-03	58.282 mi
Registration #11	2019-04-03	61.620 mi
Registration #12	2020-04-03	64.958 mi
Registration #13	2021-04-03	68.296 mi
Registration #14	2022-04-03	71.634 mi
Registration #15	2023-04-03	74.972 mi
Registration #16	2024-04-03	78.310 mi
Registration #17	2025-04-03	81.648 mi
Registration #18	2026-04-03	84.986 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1778 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	564081